LAND CORNER RECORDATION CERTIFICATE

R997869

REVISED JAN., 1983

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MACOMB Located In: STERLING TWP. Corner Code ## (County) IRER 06161M219 T 2N R 12E Public Land Survey __ R _ _ R . _ R 2. Property Controlling R _ R Τ_ in Section S S T R Miscellaneous Register of Deeds Stamp & File Number R Property in Sec. __ , Recorded Plat _ Private Claims 2 3 **NOVEMBER 18 BRUCE ANTCLIFF** 93 19 in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 6 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 12 on this certificate. Description of original monument and accessories and/or subsequent restoration: LCRC (1977) L2886,P442-1/2" RE-ROD MDOT (1990)-PK IN 1/2" PIPE/MON BOX GLO-Post, NO WITS, REMAIN PK IN 18" TREE, E'LY, 103.02'
PK IN 18" TREE, NW'LY, 156.43'
PK IN TAR JOINT OF PAV'T, SW'LY, 72.63' NE BOLT ON LIGHT POLE, SOUTH, 36,30' PK IN CENTER BACK CURB N55W, 43.95° MCRC-IRON PK IN CENTER BACK CURB, \$45W, 51.59' PK IN CENTER BACK CURB, \$35E, 36.59' MBT, NW, 46.0' 14" SYCAMORE, NE, 28.0" LCRC (1979) L3138 P839-1/2" PIPE W/PK/MON BOX PK IN CENTER BACK CURB, N50E, 32.38° MBT. SW. 93.6' SIGN POST, S82W, 75.2' NE BOLT ON LIGHT POLE, S02W, 36.3' IRON FENCE POST, WEST, 22.4 MDOT N&T IN 24" ASH, EAST, 103.41" OFFICIAL C ACT 345 ELD ON MDOT & LCRC (1974) L2500,P804-T IRON SIGN POST, S28E, 44.4 30" MAPLE, N15W, 64.51' POWER POLE, \$80E, 32,36 12" MAPLE, N55E, 83.85 Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND PK IN 1/2" PIPE/MON. BOX COR, IS IN MEDIAN APPROX, OPPOSITE THE N SIDE OF KOHL'S DEPT. STORE THIS CORNER HAS BEEN USED AS K-2 AT LEAST SINCE 1974. HOWEVER, THE LOCATION MEETIN AS MONUMENTED IS 676.94' NORTH OF THE PROPORTIONED LOCATION FOR THE CORNER. 1 SET K-2 AT THE PROPORTIONED LOCATION AND REFERENCED THIS CORNER AS A PROPERTY CONTROLLING CORNER. GROUP SET K-2 AT PROPORTIONED DISTANCE BETWEEN K-1 & K-3, ON LINE BETWEEN FOUND K-2 (PROPERTY CONTROLLING CORNER) AND K-3. Ó KVEY C. Description of monument for corner and accessories established to perpetuate locating the position of BRUCE
ANTIGLIFF
SURVEYOR
NO.
25826

LAND SURVE ACCEP SURVI CORNI SET 3/4" REBAR & MACOMB COUNTY REMONUMENTATION CAP #25826 IN MEDIAN. WITNESSES **NEW K-2 (PROPORTIONED)** SET PK&MC TAG TOP OF CURB, N52W, 29.47' SET PK&MC TAG TOP OF CURB, S63W, 29.41' SET PK&MC TAG TOP OF CURB, \$02W, 47.26' 93 DEC 22 AM 9: 03 SET PK&MC TAG TOP OF CURB, S48E, 42.83' SET PK&MC TAG TOP OF CURB, N66E, 41.31' CARMELLA SABAUGH REGISTER OF DEEDS MACOMB COUNTY, MI CHIS. "x" SE BOLT LIGHT POLE, N06E, 66.98' 12-9-93 Date FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No. .25826 BEVISED MAY 14, 1975