B997877

## LAND CORNER RECORDATION CERTIFICATE

Fill For corners in	ing Requirement of Act 74, Mich.	P.A. 1970 93 DFC 22 BM 9: 03
MACONO		1
(County)		CARMELLIA SABAUGH REGISTER OF DEEDS MACOMB COUNTY, MI
	LING TWP.	REGISTER OF DEEDS
•	R 12E L-5	MACOMB COUNTY, MI
	_ R	
	_ R	
	_ R	0.04.04.m009
2. Property Controlling S T		LIBER 06161 PD 227
in Section S T		
3. Miscellaneous S T		Register of Deeds Stamp & File Number
Property in Sec. S T	_ H	
4. Lot No, Recorded Plat		
5. Private Claims		
o. Tivato oranio		2 6 5 4 3 2
	•	3
		4 7 8 9 10 11 12
I, BRUCE ANTCLIFF , in a field survey of	NOVEMBER .22	5   1   1   1   1   1
do hereby certify that under requirements of P.A. 74,	Michigan P.A. of 1970, the corner points me	ntioned 6
in lines 1 and 2 above were in conformance with r		d in the
current manual of survey instructions of the United Management or by a decree of a Court of Law and/or	· · · · · · · · · · · · · · · · · · ·	oi caile
above were in conformance with the rules of the Mic	·	ree of a
Court of Law; established, re-established, monu	, ,	
expressed below:		10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the sa	ime town and range, may be recorde	ed 11
on this certificate.		12 31 32 33 34 35 36
		13
A. Description of original monument and acc	essories and/or subsequent restoration	on:
GLO-Post, NO WITS. REMAIN	LCRC (1978) L2918,P57-1/2" IRON/MON BOX	ZHYZ IZ
MCRC (NO DATE)-PIPE	FENCE POST, NE'LY, 72.04' FENCE POST, EAST, 42.81'	COUNTY OFFICIAL C ACT 345 ELD ON
18" BUTTONWOOD, NE, 29.9'	PK 12" APPLE TREE, SE'LY, 50.02"	15 U R 12 1
24" MAPLE, WEST, 28.2"	PK IN UTIL POLE, WEST, 25.62	OPFE GIAL GIAL
DE POLE, SW, 27.2'	LCRC (1992) L5405,P43-1/2" IRON/MON BOX	
EDISON NOTES (NO DATE)-1/2" REROD	PK N FACE UTIL POLE, WNW, 26.12'	
MONUMENT, EAST, 42.85	CL 4" CYCLONE FENCE POST, EAST, 42.75' N&T(FENN) NE FACE 14" APPLE, SE, 50.13'	周日 五世
MH, N85W, 30.95° HYDRANT, N75W, 28.8°	"+" E SIDE SIDEWALK, NW, 43.31"	OMB THE PUBLY
•		O T Z
B. Description of corner evidence found and	or method applied in restoring or ree	stablishing corner:
FOUND 1/2" IRON IN 1" PIPE/MON. B	X	
		THE A MEE
FOUND AND VERIFIED FOUR OF THE	ABOVE WITNESSES.	THE MICH
VERIFIED DISTANCE TO M-5 AS SHOWN ON WASHINGTON WOODS SUB., L.84, P.18		
VERIFIED DISTANCE TO MES AS SITE	WIN CIN WASHING FOR WOODS SOB	. #   \$1 <del>2</del>
		PEER ONDE AT AT FRA
		Q A D 1
		CEPTED RVEY 1 RNER U 1990
		EPTI VEY NER 199
		CCEPT JRVEY ORNEH F 195
		0504
		<u> </u>
C. Description of monument for corner and a	page original antablished to page turbs	locating the nosition of the corner
C. Description of monument for corner and a	pessones established to perpetuate	rocasing the position of the confict.
SET MACOMB COUNTY REMONUME	NTATION MARKER AND CAP #25826	IN EXIST, MON, BOX,
WITNESSES		The state of the s
FND "X" E SIDE S/W, N59W, 43		The second secon
FND PK N FACE PP, N80W, 26.		\$ \$ \frac{1}{2} \f
FND COR. POST 4' CYCLONE F		* BRUCE *
FND N/FENN TAG NE FACE 14*	AFFLE INCE, 5//E, 49./3	ANTCLIFF
		* SURVEYOR
	-	No. 25826
The selected location is accepted by n	e and is generally accepted by Profe	ssional Surveyors as
the best available evidence of the positi		CHAI
B () 4 0 00		12-9-93
Signed by Nucle Contact		
Surveyor's Michigan License No25826	<u> </u>	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
		REVISED MAY 14, 1975 REVISED JAN., 1983