## SURVEY & REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners	in	i iiiig voqu			FEB % 7 199/	,	
MACOMB (County)		Located In: Clinton Twp	Corner Code #		COMMISSION		
Property in Section     Miscella	<del>-</del>	T_2N_R_13E TR TR TR TR TR TR TR	Jeg #2		Register of Deeds Stam	p & File Numbe	
		150					
		ed Plat			A B C D E F G H	IJKLM	
o. i iivato			:		2 6 5 5 4 3		
					3		
I. <u>Craig P. Amey</u> , in a field survey on <u>May 24</u> , 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current menual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					4 7 8 9 10 5 6 18 17 16 15 7 8 19 20 21 22 9	11 - 12 - 13 23 - 24 23 - 24	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded					10 30 29 28 27	26 25	
on th	nis certificate.				11		
			:		12 31 32 33 34	35 36-	
A. Descrip	otion of original mon	ument and accessories and	d/or subsequent resto	ration:	13	} <u>.</u>	
Found was w Macon	none RCMC Found ¾" pipe Notes none RCMC Found 1" pipe Plans 1973 George Avendt #16034 Found ¾" pipe LCRC L2419 P871 1977 William Soderberg #17635 Found ¾" pipe LCRC L2900 P936 1993 Bruce Antcliff #25826 Found 1" rod in mon box LCRC L6161 P242						
C. Descri	ption of monument	for corner and accessories	established to perpe	tuate locating	the position of the corner:		
	ed existing found ment MI 345 D3		rebar with a 2" diar	meter alumin	um cap stamped "Macomb (	County	
13 22 31 The sele	10° 77.47' 19° 77.68' 20° 76.75' 18° 74.86' ected location is accors as the best availa	Set ½" rebar with "T Set ½" rebar with "T Set ½" rebar with "T Set ½" rebar with "T epted by me and is genera able evidence of the position	RAV" cap at back of the RAVE cap at back o	f walk if walk if walk issional	CRAIG P. AMEY PROFESSIONAL SURVEYOR No.	* 40.	
	4 0	GROUP AS THE OI PUBLIC ACT 345 ON 10-7	260	R MICHIGAN TING HELD	34970 POFESSIONAL SUP		
<b></b> -	Car	WILLIAM E.	SODERBERG, P.S., CHAIF	·	17-9.91		
Signed by		- 10		Date	· L · [ · 7 b	<del> </del>	
Surveyor's	s Michigan License	No. 34970		_			