APR 2 8 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 SEP 30 AM 9:01

For corners	in and	ANAI	CC	ON
-------------	--------	------	----	----

5. Private Claims \_\_\_

Located In: Shelby Macomb Corner Code ## Township T 3N R 12E D-1Public Land Survey T \_\_\_\_\_ R \_\_\_\_ T\_\_\_\_\_R. T \_\_\_\_\_ R \_\_\_ **Property Controlling** \_ T \_\_\_\_ R \_\_ \_\_ T \_\_\_\_\_ R \_\_ in Section Miscellaneous \_\_\_ T .\_\_\_\_ R .\_\_\_ \_ T \_ \_\_ R \_ Property in Sec.

\_\_\_\_ , Recorded Plat \_\_\_

CARMELL 48AUGH REGISTER OF DEEDS IM, YTHIOD ANDOAM

418FP 06464PF474

Register of Deeds Stamp & File Number

Huston K. Kennedy, in a field survey on \_\_\_\_ August 21 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO - No post set - No bearing trees

	^	R	<u> </u>	<u>_</u>	E_	r	G	n	1 4	_ ^		M
2	_	6						3 —		Ĭ.		
3		<u> </u>	L			<u> </u>	_		_			$\sqcup$
4	<u> </u>	] 7	<u> </u>	B	<u> </u>	] 	<u> </u> _,	<u> </u>	<u> </u> -1	1—	1	2
5		┡	<b> </b>		<b> </b>	_	<b> </b>					
6	-1	8	Ļ,	7	<u> </u>	 6	<b>L</b> ,	5	-1	4—	1	3—
7	<u> </u>	<u> </u>	╙		<u> </u>	<u> </u>		<u> </u>	ļ			
8	L_1	9	<u></u> 2	o	2	1	-2	2	-2	3—	2	4
9	ļ	<u> </u>	ļ	_	_	<u> </u>	<u> </u>	<u> </u>			_	
10	<u>_</u> 3	ļ 10	<u></u> 2	9	2	8	<u> </u> _2	7	2	6	2	5
11	<u> </u>		$ldsymbol{f eta}$		<u> </u>	_	<u> </u>	_			<u> </u>	
12	-:	l 11	<u> </u> _3	  2	-3	  3	<del> </del> _3	4	3	5	3	6
13	L	<u></u>	<u>L</u>		<u> </u>	L-	<u> </u>	<u> </u>	<u> </u>		Į.	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - I set a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument HI Act 345 #17623" on a line between the Southeast corner of Section 32 and the South 1/4 corner of Section 32, T4N, R12E, 2460.21 feet West of the Southeast corner of Section 32, which is located 215.94 feet West of the Northeast corner of Section 5, T3N, RL2E. The corner is located 71 feet North of the North edge of the West bound lane of 26 Wile Road.

## FIELD MEASUREMENT BETWEEN

D-1 to E-13 (Washington Twp.) 2460.21 Feet

D-1 to D-13 (Washington Twp.) 215.94 Feet

D-1 to C-1 2716.42 Feet

D-1 to E-1 2716.42 Feet

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1890 AT A MEETING HELD

WILLIAM E. SODERBERG, P.S., CHAIRMAN

ROFESSIONAL SUBVEYOR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-1 I set a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623".

Due West 54.01' Set PK & Remon. Washer North face Power Pole

N17 E 29.46' Set PK & Remon. Washer North face 14" Oak

N76 E 73.41' Set PK & Remon. Washer SE face 23" Oak

The selected location is a careful and faithful re-establishment of the position of the positi Managaman Lw.

623ל

Surveyor's Michigan License No

FORM APPROVED TO MICHIGAN HGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975