C126167

APR 2 8 1995

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

al.	SFP	30	ΔM	9:	0
UI I		.711	MI I	"	٠,,

	Filian Descionant of Act 74 Mich D	94 SEP 30 AM 3. 01
For corners COMMISSION	Filing Requirement of Act 74, Mich. P	<b>東東西はどう。これは行う自信性</b>
Macomb (County)	Located In: Shelby Corner Code ## Township	REGISTER OF DEEDS MACONET COUNTY, MT
1. Public Land Survèy	T 3 N R 12 E G-3  T R T R T R T R T R T R T R T T R T T R T T T R T T T R T T T T R T T T T T R T	HIBER 06464PG480
in Section S  3. Miscellaneous S	T R	Register of Deeds Stamp & File Number
f. Huston K. Kennedy in a fie do hereby certify that under requirement in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule Court of Law; established, re-established expressed below:  NOTE: Not more than 4 corners, a on this certificate.	Id survey on July 5, 19 94 soft P.A. 74, Michigan P.A. of 1970, the corner points ment ance with regulations and rules therefore as required the United States Department of the Interior, Bureau of Law and/or that the corner points mentioned in lines 3, 4 soft the Michigan Board of Land Surveyors or by a Decreshed, monumented, re-monumented, recovered, four all in the same town and range, may be recorded	2 6 5 4 3 2 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 1 1 1 2 1
1817-GLO Wampler, D.S.; Set Post	nt and accessories and/or subsequent restoration; 18" Elm S23*W 11 Links; 8" Lynn N25*W 12 Links L.2342, Pg.616 - Fnd PK Nail & MCRC Cap in blac	i e

- 2.) 1977-Avey, P.S. #15396; LCRC L.2886, Pg.974 Pnd base of PK Nail & replaced with a new PK Nail & shiner 3.) 1987-Kobs, P.S. #14097; LCRC L.4220, Pg.493 Reset PK Nail centerline of Van Dyke
- 4.) 1988-Kobs, P.S. #14097; LCRC L.4543, Pg.55 Fnd 1/2" Iron Bar in a Monument Box
- 5.) 1972-Kobs, P.S. #14097; Survey L.2342, Pg.608 Fnd PK Nail & MCRC Cap, used same wit as 1972 LCRC
- 6.) 1987-Kobs, P.S. #14097; Survey L.4220, Pg.429 Fnd PK Nail in pavement, used same wit as 1987 LCRC 7.) 1990-Kobs, P.S. #14097; Survey L.4866, Pg.878 Fnd 1/2" Iron Bar in a Monument Box, used same wit as 1988 LCRC
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 5/8" Iron in a Monument Box in the centerline of 25 Mile & Van Dyke Roads, both have bituminous surfaces.

Witnesses from LCRC #3 & 4 were used to recover and verify the location of the found 5/8" Iron in a Monument Box.

## PIELD NEASUREMENT BETWEEN

G-3 to G-2 2638.01 Feet G-3 to F-3 2665.58 Feet ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD

WILLIAM E. SODERBERG, P.S., CHAIRMAN

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - G-3 I replaced the found 5/8" Iron in a Monument Box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a existing Monument Box.

S48 W 56.24' Set PK & Remon. Washer NW face Guide Pole

S42°E 66.82' Set PK & Remon. Washer NE face Power Pole

N44°E 46.32' Set PK & Remon. Washer NW face Power Pole

The selected location is accepted by me and is generally accepted by Professional Surveyor the best are really position of the original corner. \*\*\*

Signed by Surveyor's Michigan License No.

VEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

ROFESSIONAL SURVEYOR

REVISED JAN., 1983

evidence of the