REVISED JAN.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970ECCEDED IN MACOME OCUNTY RECORDS AT: 8:30 A M. For corners in Macomb Located In: Corner Code ## Shelby Twp. DEC 28 1993 T 3 N R 12 E Public Land Survey T _____ R ____ T _____ R . T ____ R _ 2. Property Controlling __ T _____ R __ \$ ____ R _ in Section Miscellaneous S ____ R ___ Register of Deeds Stamp & File Number Property in Sec. ____ , Recorded Plat __ 5. Private Claims _ December 14 t Huston K. Kennedy, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 12 on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post; 5" Beech NO7°E 18 Lnks; 5" Beech S38 1/2°E 6 Lnks 1974-Avey, P.S. #15396; LCRC L.2496, Pg.762 - Fnd 1/2" Pipe 1974-Kobs, P.S. #14097; LCRC L.2499, Pg.414 - Fnd 3/4" Pipe 1980-Kobs, P.S. #14097; LCRC L.3217, Pg.662 - Fnd 3/4" Pipe in a monument box 1987-King, P.S. #30085; Surveys L.4151, Pg.89,94 - Fnd 1/2" Iron w/cap #17635 in monument box 1987-King, P.S. #30085; LCRC L.4151, Pg.126 - Same wits as 1987 surveys 1990-Avey, P.S. #30076; LCRC L.4983, Pg.762 - Fnd 1/2" Iron rod in monument box 1990-Avey, P.S. #30076; Survey L.4983, Pg.735 1992-Avey, P.S. #30076; Survey L.5290, Pg.298-299 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 3/4" Iron Rod in a monument box located in the centerline of 24 Mile Road, and in the centerline of Schoenherr Road to the South and 3' East of the centerline of Schoenherr Road to the North. Both are bituminous surface roads. Two witnesses from the 1990 LCRC were found and they were used to recover and verify the location of the found 3/4" Iron Rod ACCEPTED BY THE MACOMB COUNTY in a monument box. SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 **MEETING** 1990 AT 12-20-9 FRANK J. DeDECKER, PS, PE, CHAIRMAN C. Description of monument for corner and accessories established to perpetuate K-5 I replaced the found 3/4" Iron Rod in a monument box with 3/4" x 24" Iron Rod W/2" diameter aluminum cap stamped "Macomb County Monument MI Act 345 #17623" in a monument box. S48°E-49.43'-Set PK & Remon. tag in NE face Power Pole N56°E-43.88'-Set PK & Remon. tag in NW face Power Pole The selected location is accepted by me and is generally accepted by Professional Surveyors as the beat available evidence position of the original corner. _____Date_/2/14/93 Signed by _ OF DUP ANDY B Surveyor's Michigan License No.