

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

B997885

For corners in

MACOMB

(County)

Located In:

Corner Code #/

SHELBY TWP.

1. Public Land Survey

T 3N R 12E

L-13

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

Seg # 1 pm

LIBER 06161 PG 235

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							

I, BRUCE ANTCLIFF, in a field survey on NOVEMBER 22, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-Post, NO WITS, REMAIN

MDOT & LCRC(1974) L2500,P792- PK NAIL IN PAVT.
 POWER POLE, S15W, 57.43'
 TEL. POLE, N05E, 59.47'
 9" PEAR, N30E, 83.88'
 CONC. MON, SOUTH, 60.00'

LCRC (1988) L4353,P441, -PK NAIL IN PAVT
 MDOT N&T W FACE DE POLE, NNE, 59.39'
 CONC NAIL SE FACE DE POLE, NE, 118.33'
 PK NAIL SW FACE DE POLE, SE, 92.34'
 NE COR STEEL LIGHT POLE BASE, SSE, 74.47'

MDOT & LCRC(1990) L4888,P976
 COPPER CLAD ROD & CAP IN MON BOX
 MDOT N&T W FACE DE POLE, N05E, 59.46'
 CONC NAIL SW FACE DE POLE, S50E, 92.28'
 NE COR STEEL LP BASE, S25E, 75.59'
 "X" E RIM WATER MH, S40W, 64.07'
 "X" E RIM BELL MH, S15W, 66.88'

LCRC (1987) L4131,P656-PK NAIL
 N&T IN UTIL POLE, N05E, 59.47'
 N&T IN UTIL POLE, N60E, 118.10'
 PK IN UTIL POLE, S50E, 92.30'

THIS CORNER IS COMMON
 TO BOTH T2N,R12E & T3N,R12E.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND COPPER CLAD ROD & CAP/MON. BOX
 FOUND AND VERIFIED SIX OF THE ABOVE WITNESSES

93 DEC 22 AM 9:04

CARMELLA SABAUGH
 REGISTER OF DEEDS
 MACOMB COUNTY, MI

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 SET MACOMB COUNTY REMONUMENTATION MARKER AND CAP #25826 IN EXIST. MON. BOX.
 WITNESSES

FND N&T W FACE DE POLE, N11E, 59.41'
 FND CON. NAIL SW FACE DE POLE, N64E, 118.29'
 FND NE COR. STEEL L. POLE BASE, S20E, 75.63'
 FND "X" E RIM WATER MH, S45W, 64.10'
 FND "X" E RIM BELL MH, S17W, 66.42'
 FND PK IN SW FACE P POLE, S47E, 92.26'

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by Bruce Antcliff
 Surveyor's Michigan License No. 25826

Date 12-9-93

