Filing Requirement of Act 74, Mich. P.A. 1970RECORDS AT:

SHELBY

T-3-N, R-12-E

R. \_ R \_

\_ R \_

\_\_ R \_

\_\_ T <u>\_\_\_\_</u> R \_

\_\_ T \_\_

\_\_\_\_\_, Recorded Plat \_

Located In: TOWNSHIP Corner Code #

For corners in

MACOMB

1. Public Land Survey

2. Property Controlling

Property in Sec.

5. Private Claims \_\_\_\_

in Section Miscellaneous OEC 28 1993

Register of Deeds Stamp & File Number

8:30AM

## LAND CORNER RECORDATION CERTIFICATE RECORDED IN MACOME COUNTY

I. <u>DAVID PAWLACZY K.</u> , in a field survey on <u>NOVEMBER 23</u> , 19 <u>93</u> .  do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	21 22 23 24 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded  on this certificate.	33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	
POST WAS SET PER GOVERMENT LAND OFFICE RECORDS  N. 82°E, 7 LINKS 18" BLACK ASH  5, G3°W, 8 LINKS 4" ASH	OMB COUNTY THE OFFICIAL PUBLIC ACT 345 G HELD ON PS, PE, CHAIRMAN
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  FOUND V2" RE-ROD IN ASPHALT PAVEMENT  LIBER 2352, PAGE 10  LIBER 2358, PAGE 938  LIBER 2832, PAGE 30G  LIBER 3021, PAGE 208  LIBER 4479, PAGE 90  PREVIOUS LAND CORNER RECORDATION CERTIFICATES	ACCEPTED BY THE MAC SURVEY PEER GROUP AS CORNER UNDER MICHIGAN H OF 1990 AT A MEETIN 12 - (5-43 DALLA L FRANK J. DøDECKER,
C. Description of monument for corner and accessories established to perpetuate locating the position of the REPLACED 1/2" RE-ROD WITH P. A. 345 ALUMINUM CAP STAMPED # 17632 ON 3/4" × 24" IRON ROD.  ACCESSORIES ESTABLISHED  N. 80° W. G8.GI WITNESS TAG ON NORTH FACE UTILITY  N. 30° E. 42.98 WITNESS TAG ON WEST FACE UTILITY  S: 30° W. G1.79 WITNESS TAG ON WEST FACE UTILITY  DUE SOUTH 98:11 MONUMENT BOX A-5 NORTHWEST CORNE  Signed by Date 12.2493  Surveyor's Michigan License No. 1763L  FORM APPROVED BY MICHIGAN STATI	POLE POLE POLE annumenumes.