

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MACOMB
(County)

Located In: Corner Code #

RECORDED IN MACOMB COUNTY
RECORDS AT: 8:30A M.

DEC 28 1993

Carroll A. Anderson
CLERK - REGISTER OF DEEDS
MACOMB COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

- 1. Public Land Survey T B-N R 13-E C-12
- T _____ R _____
- T _____ R _____
- T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
- in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
- Property in Sec. S _____ T _____ R _____

- 4. Lot No. _____, Recorded Plat. _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, DAVID PAWLACZYK, in a field survey on NOVEMBER 29, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

POST WAS SET PER GOVERNMENT LAND OFFICE NOTES
EAST 6 LINKS 14° N 14° E 25 LINKS

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 12-15-93

Frank J. DeDecker
FRANK J. DeDECKER, PS, PE, CHAIRMAN

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

1/2" IRON ROD WAS PLACED IN ACCORDANCE WITH SURVEY PERFORMED BY MR. WILLIAM SODERBERG, B.L.S., IN DECEMBER, 1970.

PREVIOUS LAND CORNER RECORDATION CERTIFICATES
LIBER 2940 PAGE 391
LIBER 2336 PAGE 412

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

REPLACED 1/2" IRON ROD WITH P.A. 349 ALUMINUM CAP STAMPED # 17632 ON 3/4" x 24" IRON ROD.
ACCESSORIES ESTABLISHED

- N 20° E 290.41' WITNESS TAG WEST FACE U-POLE
- N 30° W 128.37' & TOP NUT FIRE HYDRANT
- S 10° W 171.72' WITNESS TAG EAST FACE 6" ELA
- DUE EAST 33.79' WITNESS TAG NORTH FACE U-POLE

Signed by *David Pawlaczyk* Date 12-24-93
Surveyor's Michigan License No. 17632

