LAND CORNER RECORDATION CERTIFICATE 93 DEC 22 AM 9: 05

For corners in	Filing Require	ement of Act 74, Mich. P.A.	. 1970	. CADAHGU
For corners in MACOMB	1	0.000	CARMELLA REGISTER	SABAUGH OF DEEDS_
(County)	Located In:	Corner Code ≠	MACOMB 0	OF DEEDS OUNTY, MI
Public Land Survey	MACOMB TWP. T <u>3N</u> R <u>13E</u> T R	E-13		·
2. Property Controlling	T R T R	No a. I m	LIBERO	6 1 611248
	S T R S T R			
	S T R S T R		Register of Dee	ds Stamp & File Number
4. Lot No, Reco			A B C	DEFGHIJKL
5. Private Claims			2 6	5 4 3 2
			3	
BRUCE ANTCLIFF in		EMBER 23 93		89-10111
do hereby certify that under require in lines 1 and 2 above were in co	ements of P.A. 74, wichigan P.A. (or 1970, the corner points mention	he 6 18 1-	17-16-15-14-1-1
current manual of survey instruction Management or by a decree of a Co	•		45	
above were in conformance with th	ne rules of the Michigan Board of	f Land Surveyors or by a Decree o	ta o i	20 21 22 23
Court of Law; established, re-esexpressed below:	stablished, monumented, re-m	ionumentea, recoverea, iouna	ا ا ام.	29 28 27 26 3
NOTE: Not more than 4 corn	ers, all in the same town an	d range, may be recorded	11	
on this certificate.			12 31	32 33 34 35 3
A. Description of original mor	nument and accessories and	/or subsequent restoration:	13	+ • · · · · · · · · · · · · · · · · · ·
GLO-Post, NO WITS, REMAIN		(1988) L4507,P853-IRON/MON BOX PP, N38E, 72.42'	LCRC (1991) L52 IN MON BO	90,P292-1/2" IRON #31610 DX
LCRC (1972) L2302,P904- MON BOX	X MDOT N&T IN F	PP, N27W, 66.38'	PK/DISK #215631	NW SIDE PP, NE, 72.51'
SW'LY RIM STORM MH, N45E, 40.00 SE'LY RIM STORM MH, N45W, 41.60 PK IN DE POLE, S45W, 69.55'		PP, \$36W, 70.50' LE, \$11E, 113.17' 2670.82'		, 9E, 75.01 SW SIDE PP, NW, 66.58* NW SIDE PP, SW, 70.48*
LCRC (1978) L2940,P350-IRON IN M PK&T IN UTIL POLE, NE'LY, 72.55' MDOT N&T IN UTIL POLE, SE'LY, 11 MDOT N&T IN UTIL POLE, SE'LY, 69	PK/DISK #2156; 13.14' PK/DISK #2156; 9.63' PK/DISK #2156;	1723,P608-EMPTY MON BOX 3 W SIDE PP, N37E, 72.32 3 N SIDE PP, S73E, 120.89 3 NW SIDE PP, S33W, 70.67		UNTY ICIAL ST 345 ON IRMAN
PK&T IN UTIL POLE, NWLY, 66.64' 3. Description of corner evide	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	3 sw side PP, N37W, 66.45' pplied in restoring or reestabl	lishing corner:	SEAU TE
Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 1/2" ROD W/MDOT CAP IN MON. BOX				OMB (THE COURTED OF HEICOURTER
FOUND AND VERIFIED THREE OF THE ABOVE WITNESSES				
VERIFIED MDOT DIST	ANCES TO D-13, T3N, R13E	E AND TO E-1, T2N, R13E		THE MACHIGAN MICHIGAN MEETIN
				THE NGROUP MICHIGA MICHIGA MEE
2				PEER CUNDER AT AT FRANK
				E S S S S S S S S S S S S S S S S S S S
C. Description of monument for	or corner and accessories e	stablished to perpetuate loca	ting the position of	N See See See See See See See See See Se
	Y REMONUMENTATION MA	ARKER AND CAP #25826 IN E	XIST. MON. BOX.	S STREET
FND MDOT N&T	IN SE FACE P POLE, N37E IN E FACE P POLE, N28W,	66.38'	á	288
	TIN'SE FACE P POLE, S33W MC TAG IN NW FACE P POI			BRUCE ANTCLIFF SURVEYOR No. 25826
	s accepted by me and is gen ance of the position of the orig		•	OF LAND
signed by Bruce Ch	steliff	Date	-9-93	
Surveyor's Michigan License No	o. 25826		DRM APPROVED BY MICHIGAN ST	ATE BOARD OF LAND SURVEYORS, JAN. 28,