B997901

## LAND CORNER RECORDATION CERTIFICATE

For	corners in		Filing Require	ment of Act 74, Mich. P.A.	197 <b>0</b>	
roi	MACOMB			ſ		
	(County)		Located In:	Corner Code ##		
1	Public Land Survey		MACOMB TWP.	⊔ 49		
1.	Public Land Survey		Т <u>3N</u> R <u>13E</u> ТR	H-13		
			T R		(	06 <b>1</b> 6 <b>1</b> %25 <b>1</b>
			<u>T</u> R		LIBER	NOTOTUKUT
2.	Property Controlling in Section		T R T R			
3.	Miscellaneous		T R		Danistas of Da	ada Dia ana 0 Ett. Maria
	Property in Sec.	s			Register of De	eds Stamp & File Number
Л	1 of No	Racorda	d Diat			
5.	Private Claims		J Flat		A B C	DEFGHIJKL
			,		2 6	-541-
					3	
1,	BRUCE ANTCLIFF	., in a fi	eld survey onNOVE	MBER 23 , 19 <u>93</u>	5	- 8 - 9 - 10 - 11 - 12 - 1   1   1   1   1
do h	ereby certify that under re	equiremen	ts of P.A. 74, Michigan P.A. o	of 1970, the corner points mentioned I rules therefore as required in th	d 6 18	17 16 15 14 13
curr	ent manual of survey inst	tructions o	f the United States Departm	nent of the Interior, Bureau of Land	d 7	
				points mentioned in lines 3, 4 and Land Surveyors or by a Decree of	· · · · · · · · · · · · · · · · · · ·	-20-21-22-23-24
Cou	rt of Law; established,			onumented, recovered, found a	s 9	
•	essed below:				10 30	-2 <del>9</del> -2 <del>8</del> -27 - 26 - 25
NO	on this certificate		all in the same town and	d range, may be recorded	11 12 31	32 33 34 35 36
		-			13	32 33 34 35 36
	•		ent and accessories and	/or subsequent restoration:		_
G	CLO-Post, NO WITS, REMAIN	İ				도 가 수 도
	IDOT & LCRC (1988) L4578,F C'S RIM WATER MH, N05E, 5			ELD NOTES (1988) PK NAIL F HYDRANT, NNE, 48.33'		OOUNTY OFFICIAL S ACT 345 SLD ON
۲	OP CENTER HYDRANT, N25	E, 48.28'	SE COR ROAD (	C.B., NW, 48.97'		ACI PER LA PERPER LA PERPER LA PER LA
T	35E, "X" S RIM WATER MH, S OP CENTER HYDRANT, S15	E, 52.86'	CENTER HYDRA BACK OF CURB	, NORTH, 24.12'		lei Ecga
	(" S RIM STORM MH, S35E, 7 IDOT N&T IN 12" ASH, N65W		PK &T#17635 TC	OP OF CURB, NE, 26.61'		그 주문 신째
						8 F E S
₿.	Description of corner	evidence	found and/or method ap	oplied in restoring or reestablis	shing corner:	\$35E . 38
	FOUND PK NAIL					HIGAN WEETT MEETT MEETT MEETT MEETT MEETT
	FOUND AND VERIFIED SIX OF THE ABOVE WITNESSES.					HSEX CAR
	FOUND AND VER	IFIED SIX	OF THE ABOVE WITNE	:SSES.		FRZ Zn MA
						N G ON NX
						MADE: RE
				93 DEC 22 AM 9: 05		# # 8 % Z
				CARMELLA SAB <b>AUGH</b>		CEPTI RVEY RNER 199
				REGISTER OF DEEDS MACOME COUNTY, MI		
				MACOME CUUNIY, MI		00 St
C. i	Description of monum	ent for co	orner and accessories es	stablished to perpetuate location	ng the position o	f the corner:
				RKER AND CAP #25826 IN NE		. « አስትስሽሽሽሽ የተ
	WITNESSES					OF MICH.
			RGATE MH, N10E, 53.00 ANT, N32E, 48.22'	0'		
			RGATE MH, S30E, 53.18	3'	Ž	* BRUCE *
			ANT, S10E, 52.99'		\$	* ANTCLIFF
			M MH, S42W, 73.44' PP OF CURB, N32E, 26.6	32'	3	SURVEYOR No.
	i no i no m	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		<del>-</del>	4	25826
	The 13-1-11- 0			andle accepted by Duffers	I C	MACO LAND STATE
		The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.				
	2	Q. +.	0:00	Date 12-9	9-93	
~	su by	Jane	A DEODE	Date	<u> </u>	
Surve	eyor's Michigan Licens	se No	25826	FOR	M ADDROVED BY MICHIGAN	STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983