## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

## SURVEY & REMONUMENTATION

|  | Filing Requireme  | nt of Act 74, Mich. P.A. 1   | 1970  |   |
|--|---|--|---|---|
| For corners in   |   |  | APR 0 7 1998  |   |
| MACOMB (County)  | Located In:<br>MACOMB   | Corner Code #  |   |   |
| (County)   | WACOWB  |  | SECTION   |   |
| 1. Public Land Survey  | T 3N R 13E<br>T R T R   | M-12   |   |   |
| 2. Property Controlling in Section S 3. Miscellaneous S Property in Sec. S   |   |  | <br>  | 7 |
| 4. Lot No, Recorded Pl   |   |  | Register of Deeds Stamp & File Number   |   |
| 5. Private Claims  |   |  |   |   |
| I, STEVEN E. DUNN, in a frie do hereby certify that under requirements o mentioned in lines 1 and 2 above were in c as required in the current manual of survey Interior, Bureau of Land Management or by points mentioned in lines 3, 4 and 5 above Board of Land Surveyors or by a Decree of monumented, re-monumented, recovered, | f P.A. 74, Michigan P.A. of 197 onformance with regulations a rinstructions of the United State y a decree of a Court of Law an were in conformance with the roa Court of Law; established, r | 0, the corner points and rules therefore s Department of the d for that the corner ales of the Michigan                    | A B C D E F G H I J K L  2  | M |
| NOTE: Not more than 2 corner recorded on this certi  |   | and range, may be  | 8 19 20 21 22 23 24<br>9 10 30 29 28 27 26 25   | - |
| A. Description of original monument  | and accessories and/or subse  | equent restoration:  | 12 31 32 33 34 35 36  | - |
| A. Description of original moniment ar   | nd accessories and/or subse   | quent restoration:   | 13  |   |
| GLO POST-NO EVIDENCE OF ORIGIN   | AL CORNER FOUND-ORI   | GINAL GLO SURVEY PERFORM   | MED BY WILLIAM PRESTON-1824   |   |
| DEED:<br>L. 524, P. 493 JULY<br>L.C.R.C.   | ·<br>′ 6, 1943  |  |   |   |
| L. 6166, P. 61 SHELBY W. MC  | NEY #30092 FOU  | ND BOAT SPIKE, SET REMON   | CORNER DEC. 28, 1993  |   |
| UNRECORDED SURVEYS: TOPO SURVEY CERTIFICATE OF SURVEY ALTA/ACSM SURVEY   |   | AEW JOB #095-336<br>PEA ASSOC. JOB#96067S<br>METCO SERVICES JOB#9  |   |   |
| FOUND 1/2"IRON ROD IS 109<br>#21563 NEARLY MATCHES O<br>EASTERLY RIGHT-OF-WAY I<br>THE EASTERLY RIGHT-OF-V   | P#21563. CORNER IS COMM<br>0.24" NORTH OF PREVIOUS<br>FALL IN DEED RECORDED<br>LINE OF GRATIOT AVE. (A)<br>VAY LINE OF GRATIOT AV   | 40N CORNER TO A-12, T.3N., R.:<br>BLY RECORDED REMON. COR!<br>IN L. 524, P. 493 OF 189.34' (18<br>BSUMED BY ME, NOT CALLED | .14E.<br>NER (L.C.R.CL.6166,P.53). FOUND 1/2" IRON ROD W/CA<br>88.85' MEAS.) FROM SAID WEST 1/4 CORNER NORTH TO<br>OUT AS SUCH IN DEED). THE DEFLECTION ANGLE OF<br>SECTION 31 IS ± 00°04'00" OF RECORD PER DEED. |   |
| FIELD MEASUREMENTS AND RECOP<br>M-12 TO M-11<br>GLO-40 CHAINS OR 2640.00'<br>FIELD-2700.98'  | RD MEASUREMENTS:  | M-12 TO M-13<br>GLO-40 CHAINS<br>AEW-2676.86'  | G OR 2640.00'   |   |
|  |   | FIELD-2676.85  |   |   |
| C. Description of monument for corner M-12 T.3N., R. 13 E.   | and accessories established   | o perpetuate locating the position   | n of the corner:  |   |
| COUNTY MONUMENT<br>NOTE: THIS POSITION S   | MI, ACT 345" #28408.  | TH A 3/4"x24" IRON ROD WITH<br>ECORDED IN L. 6166, P. 53   | A 2" DIAMETER ALUMINUM CAP STAMPED "MACOMB  |   |
| S.54°E. 7.53' FOU<br>S.10°W. 20.27' FOU  | ND NAIL IN NORTH FACE!<br>ND NAIL IN WEST FACE 7  | .M, REPLACED IT WITH MAG N<br>5" POPLAR, REPLACED IT WITH<br>POPLAR, REPLACED IT WITH<br>" ELM, REPLACED IT WITH MA        | TH MAG NAIL & METCO TAG<br>HMAG NAIL & METCO TAG  |   |
| THE SELECTED LOCATION IS ACCE<br>EVIDENCE OF THE POSITION OF TH  |   | RALLY ACCEPTED BY PROFES   | SSIONAL SURVEYORS AS THE BEST AVAILABLE   |   |
| •  | GROUP AS  | BY THE MACOMB COUNTY SE<br>THE OFFICIAL CORNER UNDE<br>CT 345 OF 1990 AT A MEE   | ED MICHAEL S  |   |

Signed by Staven C. Surveyor's Michigan License No. 28408

A MEETING HELD

A MEETING HELD

PROFESSIONAL SURVEYOR
NO.
28408

Date

Date

Date

18, 1997

WILLIAM E. SODERBERG, P.S., CHAIRMAN