LAND CORNER RECORDATION CERTIFICATE

Foi	r corners in	Filing Re	quirem	ent of Act 74, M	lich. P.A. 1970 REC	<mark>O</mark> RDED IN MA ORDS AT:	COMB COUNTY 8:30 A	, М.	
					1		V , V = ···		
	MACOMB	Located In:	L ma	Corner Code #	t				
	(County)	Maco	nb Town	usurþ		DEC 2	8 1993		
	6.44.1.16	T 3N R 1	3 E	M-13					
1.	Public Land Survey		-				_		
		T R			—]		The travers	/	
		T R			- 1 Z	Britan red Blow	a golden ticknehmen	-energy	
		T R			ÇLE	PERFECTIONS	OF DEEDS		
2	Property Controlling	S T R			MAC	COMB DOUBLE	MICHIGAN		
۷.		S T R :							
	in Section				_ _		l- O4 O F	Tile Niverbay	
3.	Miscellaneous	S R			Re	egister of De	eds Stamp & F	·lle Number	
	Property in Sec.	S T R							
4	Lot No.	, Recorded Plat		a)		– авс	DEFG	HIJKE	_ M
5.						_ []			Т
٠.	,a.v o.a					2 - 6-	- 5 - - 4 - -	3-1-2-1	1 —
						3			
								10 11	12_
			,	10	0.3	7 - (-	- 1 - 1 - 1 - 1		
١, _	Shelby W. Money	, in a field survey on N	ovempe.	<u>r 18 </u>	19 93	5	- 	+++-	
do	hereby certify that under	requirements of P.A. 74, Michig	an P.A. of 1	970, the corner poin	itsmentioned	618	1716	15-14	13—
in	ines 1 and 2 above wer	e in conformance with regulati	ons and ru	les therefore as re	quirea in the	7			
cu	rrent manual of survey in	structions of the United States	Departme	nt of the interior, Bu	ireau of Land				I
Ma	anagement or by a decree	of a Court of Law and/or that the	corner po	oints mentioned in ill	nes 3, 4 anu 5	8 - 19-	2021	22 - 23 - 2	24
ab	ove were in conformance	with the rules of the Michigan E	soard of La	and Surveyors or by	a Decree or a	9	-	 	
		, re-established, monumente	d, re-mon	iumentea, recovere	ed, lound as	10 _ 30		27 26 2	25
	pressed below:					30	-2920	2,—1 20 -	آ
NO	OTE: Not more than	4 corners, all in the same to	wn and i	range, may be red	corded	11	1 1 1 -	 	+
	on this certifica					1231	_32 3-	3435	36—
						13			Щ,
В.	#ACCHB COUNTY ROAD COMMISSI OMESTERFIELD TOWNSHIP / COM- FOUND 3/4" IRON FIPE N 17- 8 43.79 PP N 17- 8 43.79 NAIL (N 54- 8 46.10; NAIL (N 53- W 26.33; NAIL (CLINTON TOWNSHIP / CONTROLL S 67- 8 83.23; PK IN N 50- 8 32.55; PK IN N 50- W 17.13; PK IN Description of corne FOUND 1" PIPE THIS CORNER N	ON (1934) MROLLING IN SECTION 31, T.3N., R.1 OW SUFFACE IN A 12" EM TREE IN CAP IN A 25" OAK TREE IN CAP IN A 12" EM TREE IN CAP IN TELEPHONE POLE IN THE SOUTHERES FACE OF A 4" OAK TREE THE SOUTHEREST FACE OF A 4" OAK TREE	4E. CORNER SODERBERG # CORNER	S 67: E N 67:	83.23.7 PK IN 32.55.7 PK IN 57.06. PK IN 17.13. ST. PK IN 17.55.	L. 4686 P. P. TOULLING IN SECTION	MACOMB	COUNTRICE COUNTRICE	E 502
		•			0	and.	la .		
					FRAI	NK J. DeDF	CKER, PS, P	E. CHAIRM	AN
_	Description of many	ument for corner and access	ories est	ablished to perne			<u>`</u>		
U	·	PIPE WITH 3/4" BAR MACOMB (is because,	45	THE PARTY OF	
	WITNESSES:						ESEO.	F MICHIC	d'
	N 05 N 40	9 W 19.59 FOUND PK NAIL	IN THE N	ORTHEAST FACE OF	A 4" BASSWOOD	TREE	Agr.	4	V
	EAST SOUT	H 60.34' FOUND PK NAIL	IN THE N				# SH	IELBY W. WONEY	*

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

___ Date 12-15-93 poney 30092 Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN.. 1983

SURVEYOR