UBER 05165M970

B999603

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.Apt 970 co as suppose

For corners in	i iiiig nequite	ment of Act 14, mich.	RECORDS AT: 8:30 A M.	
Macomb	Located In:	Corner Code ##	11.00 NG NS. 8.30 A M.	
(County)	Chesterfield		00000000	
4 Dublic Land Conser	т <u>ЗМ</u> в <u>14 Е</u>	E-5	DEC 2 S 1993	
Public Land Survey	T R	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>		
	T R			
	T R		Carmella formand	
2. Property Controlling	S T R		CLERK - REGISTER OF DEEDS MACOMB COUNTY, MICHIGAN	
in Section	S T R			
3. Miscellaneous	S R		Parietas of Doods Plans & File	Ni
Property in Sec.	S T R		Register of Deeds Stamp & File	Number
, , , , , , , , , , , , , , , , , , , ,	, 			
4. Lot No, R	Recorded Plat	<u> </u>	A B C D E F G H	i.t K M
	•		2 - 6 - 5 - 4 - 3 -	-
			3	
			4 - 7 - 8 - 9 - 10 -	11-12
ı, <u>Steven E. Dunn</u>	, in a field survey on December	<u>4</u> , 19 <u>93</u>	5 1	
do hereby certify that under rec	quirements of P.A. 74, Michigan P.A. o	of 1970, the corner points me	entioned 6 18 17 16 15	14-1-13-
	n conformance with regulations and uctions of the United States Departr			
	a Court of Law and/or that the corner		OLANO	
	th the rules of the Michigan Board of		cree of a	23 24
	re-established, monumented, re-m		ound as	
expressed below:			10 30 29 28 27	26 -25
NOTE: Not more than 4 c	orners, all in the same town an	d range, may be recorde	ed 11	
on this certificate.			12 31 32 33 34	35 36
			13	<u> </u>
 A. Description of original in 	monument and accessories and	or subsequent restorati	ion:	
GLO Post - No e	vidence of original co	rner found.	•	
GLO Original su	rvey performed by Pres	ton 2-18-1818.		
T C D C • T 2/	74, P.633 Robert L. S	mith #16052	February 13, 1974	
	.05, P.603 Raymond J.		January 8, 1987	
		Donnelly #21563	September 15, 1989	
2	25, 11005 114, 11014 01	,	50,000,000	
	vidence found and/or method a	anlied in restoring or re-	ogtablishing garner:	
•			establishing corner.	
E-5 Found 1/2"	' Iron Rod in monument	box.		
Found corner ma	tches corner described	in above L.C.R.C	C's and found witnesses.	
Replaced with M	lacomb County Monument	Marker #28408 on	3/4" X 24" Iron Rod.	
•	ACCEPTED	BY THE MAC	OMB COUNTY	۸.
	CLIPVEY PF	ER GROUP AS	THE OFFICIAL	The same of the sa
	CORNED IIN	DER MICHIGAN	PUBLIC ACT 345	6, 4
	COMMER ON	AT A MEETIN	IG HELD ON STEVEN E	/~.\{
	12-15-	77 Tr Marine	® 41 DONN	**
	12-13-	17	LAND	Ž
		σ . 1000	SURVEYOR No. 28408	101
	-	shank Jall		4,3
C. Description of monume	ent for corner and accessories	Stabilished to be better	boating the position of the company	
			TAND 3	
E-5, T.3N.,R.14		0//11 77 0/11 7	2 1 (1	
-	lonument Marker #28408	on 3/4" X 24" 1rc	on Rod in monument box.	
Witnesses:	071 - 1 777 11 /266			
	.87' Found PK nail w/MC			
	15' Found 1/2" Iron Ro			
	20' Found PK nail w/RJ			
			ag in West face 28" poplar.	
N.67°E 82.	40' Found PK nail in S	E face utility po	ole.	
m1 1 1 . 4	and and the second second	.a f	motion of the modition of the	omioi1
	cation is a careful an	a raithrui perpet	cuation of the position of the	e original
corner.	p A			
Signed by Steven	E. Dunn	Date	12.20.93	
Surveyor's Michigan Licens			FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURV	EYORS JAN 28 197
Surveyor s whomgan Election				EVISED MAY 14, 197