SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

C150809

For corners in		,	LIBER 6523 PAGE 956	
MACOMB		mer Code #	94 DEC -9 PM 2:51	
(County)	CHESTERFIELD		34 PEC -3 PM 2: 51	
1. Public Land Survey	T <u>3N</u> R <u>14E</u> TR TR	<u>H-7</u>	CARMS ABAUGH REGIST OF DEEDS MACOME COUNTY, MI	
Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number	
5. Private Claims 1, STEVEN & DUNN do hereby certify that und mentioned in lines 1 and	ler requirements of F.A. 74, Michiga 2 above were in conformance with	on APRIL 4, 19 94 n P.A. of 1970, the corner po	pints 7 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be			nt of 2	
NOTE: Not more that recorded on this o		n and range, may be	ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN	
A. Description of original	monument and accessories and/or s	subsequent restoration:	PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 10-18-9+	
GLO POST - NO E GLO ORIGINAL S	EVIDENCE OF ORIGINAL CORNER FO SURVEY PERFORMED BY PRESTON 2	OUND 2-18-1818	WILLIAM E. SODERBERG, P.S., CHAIRMAN	
SKETCH OF SUR L. 2336 P. 45: L. 2547 P. 43: L. 3123 P. 25:	3-454 WILLIAM E. SODERBERG, #1 9 ROBERT L. SMITH, #16052	FOUND 1/2" IRON RO	D IN MONUMENT BOX D IN MONUMENT BOX D IN MONUMENT BOX D IN MONUMENT BOX JULY 3, 1979	
L. 2302 P. 91- L. 3168 P. 26	0 JOHN R. FENN, #23505	FOUND 3/8" IRON RO	D IN MONUMENT BOX OCTOBER 12, 1979	
B. Description of corner	r evidence found and/or method appli	ed in restoring or reestablishin	g comer:	
H-7 1/4 CORNEJ FOUND 1/2" IRO OF ABOVE L.C.R FOUND WITNES L. 3945, P. 71	ON ROD IN MONUMENT BOX IN CONC R.C.'s AND COMPARED M-DOT DISTAL IS TIES 15 N.W. 70.33' FOUND FORM NAI	CRETE PAVEMENT . VERIFIE NCES TO THE SECTION CORN L IN MSHD DISK IN FACE OF U L IN DISK IN SOUTHEAST FAC	DLOCATION BY COMPARING FOUND WITNESSES ERS TO THE EAST AND WEST. TILLITY POLE E OF UTILLITY POLE	
PROF IS MORSTID	EMENTS AND RECORDED DISTANCE	es.	STEVEN E. DUNN *	
H-7 TO G-7	2719.03' (M.) G.L.O. 2645.94' (R.) 2714.42' (M.) G.L.O. 2640.00' (R.)	- +,	STEVEN E. DUNN PROFESSIONAL SURVEYOR No. 28408 The position of the comer:	
C. Description of monum	nent for comer and accessories estab	lished to perpetuate locating t	the position of the corner:	
H-7 T.3N., R.14	E. I REPLACED 1/2" IRON ROD STAMPED "MACOMB COU!	WITH 3/4" x 24" IRON ROD W ITY MONUMENT MI. ACT 345	VITH 2" DIAMETER ALUMINUM CAP #28408" IN MONUMENT BOX.	
WITNESSES				
AZ. 165°		AG IN WEST FACE OF UTILITY	POLE.	
AZ. 0°				
AZ. 80° 7	•			
AZ. 301° 1	34.58' FOUND FORM NAIL AND A P	K IN SOUTHEAST FACE OF UTIL	ITY POLE	
THE SELECTED	LOCATION IS ACCEPTED BY ME AND	O IS GENERALLY ACCEPTED B INER.	Y PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE	

28408

Surveyor's Michigan License No.