1024258 LIBER:09054 PAGE:805 09:25A 08/17/1999 CARNELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Micr. P. For corners in	A. 1870
Macomb Located In: Corner Code # (County) Washington Township	
1. Public Land Survey	ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD
T	WILLIAM E. SODERBERG, P.S., CHAIRMAN Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ARCDEFGHIJKLM
. United M. Monnody in a field suprey on Amril 11 1999 a hereby state that	under 4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above we conformance with regulations and rules therefore as required in the current manual of survey instructions United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Mit Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monuments	of the and/or 6 19 17 16 15 14 13 chigan
recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9 10 30 29 28 27 26 25
on this certificate.	11 12 31 32 33 34 35 36 13
 A. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post 36" Black Oak S57°E 10 Links; 8" White Oak N61°W 70 Links 1.) 1971-Avey, PS #15396; Survey L.2252, Pg.226 – Set a ½" capped Iron Rod, no witnesses 2.) 1977-Kobs, PS #14097; Survey L.2811, Pg.753 – Fnd a ½" Iron Bar w/cap #15396 3.) 1977-Avey, PS #15396; Survey L.2865, Pg.252 – Object found not stated, no witnesses 4.) 1986-Kobs, PS #14097; Survey L.4055, Pg.658 – Fnd ½" Iron Bar w/cap #15396, used same wit as 1977 Survey 5.) 1973-"MT. VERNON VILLAGE SUBDIVISION NO. 1", Liber 64, Pages 17-19 6.) 1975-"MT. VERNON VILLAGE SUBDIVISION NO. 2", Liber 66, Pages 4-7 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1999-Kennedy Surveying, Inc. – Kennedy, PS #17623 - Fnd a 4" Concrete Monument located 1.30 feet South and 1.00 feet West of a 2-1/2" diameter Chain Link Steel Fence Post. A fence-tree row extending to the East, West & South. 	
Witnesses from Survey #1 & 3 were used to recover and verify the location	
I accepted the found 4" Concrete Monument as the best evidence of the	original corner positon.
C-8 to C-7 GLO = 40 chains or 2640.00 Ft. No recorded distances 2659.67 Ft. (MEA 1999) C. Description of monument for corner and accessories established to perpetuate to the corner and accessories established	ber 2865, page 252 = 2650 93 FT FESSIONAL AGE
"Macomb County Monument, MI Act #345", PS #17623 N40°W 26.68' Set Mag Nail & Remon Washer SW face 7" Cherry S04°E 37.92' Set Mag Nail & Remon Washer NE face 38" Twin Cherry S84°E 29.60' Set Mag Nail & Remon Washer South face 31" Twin Cherry N63°E 23.50' Set Mag Nail & Remon Washer SE face 9" Apple	
The selected location is accepted by me and is generally accepted by Profithe position of the original corner.	Tessional Surveyors as the best available evidence of the $8-5-99$
Signed by:	