# SURVEY & REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

APR 0 7 1998

For corners in	SECTION
Hacomb Located In: Corner Code # Washington Township	
1. Public Land Survey  T 4N R 12E F-1  T R  T R  T R  T R  T R  1. Property Controlling S T R  in Section S T R  Property in Sec. S T R	ACCEPTED BY THE MACOMB COUNTY SURVEY PEE GROUP AS THE OFFICIAL CORNER UNDER MICHIGA PUBLIC ACT 345 OF 1990 AT A MEETING HEL ON
4. Lot No , Recorded Plat 5. Private Claims	ABCDEEGHIJKLM
5. Private Claims	2 - 6 5 4 3 2 1 - 1
I. <u>Huston K. Kennedy</u> , in a field survey on <u>5/8</u> , 19 97 do hereby state that us requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan of Land Surveyors or by a Decree of a Court of Law, established, re-established, monument recovered, found as expressed below:  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	d /or 6 10 17 16 15 14 13
	13
1817-GLO Wampler, D.S.; Post Not Section Section 1817-GLO Wampler, D.S.; Post Not Section 1977-Kobs, PS #14097; LCRC L.2882, Pg.478 - Fnd 1/2" Iron Bar  1.) 1977-Kobs, PS #14097; Survey L.2590, Pg.332 - Object found not stated, no w 3.) 1975-Kobs, PS #14097; Survey L.2882, Pg.430 - Fnd 1/2" Iron Bar, used same 4.) 1977-Kobs, PS #14097; Survey L.4220, Pg.445 - Fnd 1/2" Iron Bar, used same 5.) 1977-Kobs, PS #14097; Survey L.4220, Pg.445 - Fnd 1/2" Iron Bar, used same 6.) 1990-James, PS # ; Survey, L.4947, Pg.329 - Pnd P.K. Nail  B. Description of corner evidence found and/or method applied in restoning or reestablish 1997 Kennedy Surveying, Inc Kennedy, PS #17623 - The corner has since been pe 2 feet South of the existing centerline of 32 Mile Road extending to the Ea as recovered is 0.67 feet South of the township line. Found a 1/2" Iron whi of Section 33, T5N, R12E, Bruce Township (F-13), which is located 360.14	ing corner:  rpetuated with 1/2" Iron Rod 2" below the surface and rpetuated with 1/2" Iron Rod 2" below the surface and st & West, which has a bituminous surface. The corner ich is being used and accepted as the South 1/4 corner feet to the West.
Witnesses from LCRC #2 were used to recover and verify the location of the corner.	
See back side of LCRC for Field Neasurements	
Due South 26.42' Set PK & Remon Washer Wist race 32' State 54.48' Set PK & Remon Washer NE face 27" Elm N66'E 64.98' Set PK & Remon Washer SE face 36" Oak N63'W 114.16' Set PK & Remon Washer SW face 26" Oak West 360.14 feet, South 1/4 corner of Section 33, T5N, R12E, Bruce Twp., The selected location is accepted by me and is generally accepted by Profess position of the original corner.	st 69.23 feet found 1/2" Iron Rod uth 60.09 feet found 1/2" Iron Rod  (F-13)
	D BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197

## PIELD MEASUREMENTS BETWEEN

## <u>F-1 to E-1</u>

No GLO Survey dated 5/19/77, L.2882, Pg. 430 = 2595.31 Ft. GPS-MEA = 2664.50 Ft. or GROUND CAL. = 2664.74 Ft.

#### <u>F-1 to F-13</u>

No GLO
GPS-MEA = 360.11 Ft. or GROUND CAL. = 360.14 Ft.

### F-1 to G-1

No GLO GPS-MEA = 2666.77 Ft. or GROUND CAL. = 2667.01 Ft.

> C0568788 LIBER:07613 PAGE:799 10:28A 09/02/1997 CARMELLA SABAUGH-MACOMB COUNTY, MI REG/DEEDS