SURVEY & REMONUMENTATION

APR 2 8 1995

Property in Sec.

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

. 1	C105001
	LIBER 06415PG478
٠.	94 AUG -5 PM 1: 42 CARACILLA SABAUGH MACOME PAGE DEEDS

For corners in Washington Located In: Township Corner Code ## Macomb (County) T 4 N R 12 E Public Land Survey T _____ R ____

T R T _____ R __ Property Controlling S. _ T R ... ___ R __ S in Section __ T __ Miscellaneous S _

Register of Deeds Stamp & File Number

4. Lot No. __ , Recorded Plat _ Private Claims

_ T _

, 19 . 94 I Huston K. Kennedy , in a field survey on _ June 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 12
- Description of original monument and accessories and/or subsequent restoration:
- 1817-GLO Wampler, D.S.; Set Post; 20" White Oak N16*E 30 Links; 14" White Oak S40*E 68 Links
- 1.) 1979-Verba, P.S. #13603; LCRC L.3074, Pg.11 Fnd 1/2" Re-rod inside of a Monument Box.
 2.) 1980-Kobs, P.S. #14097; LCRC L.3295, Pg.780 Pnd 5/8" Iron Bar in a Monument Box.
- 3.) 1987-Stonerock, P.S. #13601; LCRC L.4185, Pg.91 Fnd Monument Box.
- 4.) 1980-Kobs, P.S. #14097; Survey L.3295, Pq.766 Fnd 5/8" Iron Bar in a Monument Box, used same wit 1980 LCRC
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1994 Kennedy Surveying, Inc. Kennedy, P.S. #17623 Fnd 5/8" Iron Rod in a Monument Box 3.8' South of the centerline of 29 Mile Road. which has a bituminous surface, and a tree & fence row extending to the North and South.

Witnesses from LCRC #1, 2 & 3 were used to recover and verify the location of the found 5/8" Iron Rod in a Monument Box.

FIELD MEASUREMENT BETWEEN

F-7 to E-7 2653.96 Feet F-7 to G-7 2720.94 Feet

Surveyor's Michigan License No.

ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHGAN PUBLIC ACT S45 OF 1990 AT A MEETING ON 7-19-99

WILLIAM E. SODERBERG, P.S., CHAIRMAN

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-7 I replaced the found 5/8" Iron Rod in a Monument Box with a 3/4" x 24" Iron Rod w/2" diameter aluminum cap stamped "Macomb County Honument MI Act 345 #17623" in a existing Monument Box.

NO5°E 33.88' Set PK & Remon. Washer West face Power Pole

S05°W 55.65' Set PK & Remon. Washer NW face 23" Oak

S30°W 77.56' Set PK & Remon. Washer NW face 18" Oak

S70°W 84.38' Set PK & Remon. Washer NW face 18" Oak

The selected location is accepted by me and is generally accepted by Professional Surveyors as the beg position of the original corner.

Date ___ Signed by .

FORM APPROVED BY MICHIGAN STATE BOARD OF TAND SURVEYORS, JAN. 28, 1971

MAN OF MICHALL

REVISED JAN., 1983