LAND CORNER RECORDATION CERTIFICATE
RECORDED IN MACCINE COUNTY
RECORDED AT: 21 74 4 1

Fo	r corners in			MECORES ATT 8:30 A- M.	
N	Macomb	Located In:	Corner Code ##		
	(County)	Washington Twp.		DEC 2 8 1993	
		_	C 12	W O 2550	
1.	Public Land Survey	T <u>4</u> R <u>12</u>	G-13		
		T R		1	
		T R		Controlle gradience	
		T R		MACOMB COUNTY, MICHIGAN	
2	Property Controlling	S T R		The state of the s	
•	in Section	S T R			
2					
3.		S T R	F	Register of Deeds Stamp & File Number	
	Property in Sec.	S T R			
4.		Recorded Plat		— A B C D E F G H I J K L M	
5.	Private Claims			,	
				2 - 6 - 5 - 4 - 4 - 3 - + 2 - 1 - 1 - 1	
				3 	
_				4 7 8 9 -1 10 11 -12	
ı I	Huston K. Kennedy	, in a field survey onDec	ember 10 ₁₉ 93	5	
do	do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned				
in	in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				
	current manual of survey instructions of the United States Department of the Interior, Bureau of Land				
		a Court of Law and/or that the corner po		8 19 20 21 22 23 24	
		ith the rules of the Michigan Board of La		9	
		re-established, monumented, re-mor	umented, recovered, found as	10 30 39 38 37 36 35	
-	pressed below:				
NC	OTE: Not more than 4 o	corners, all in the same town and	range, may be recorded	11	
	on this certificate.	•		12 31 32 33 34 35 36	
				13	
A.	Description of original	monument and accessories and/o	r subsequent restoration:		
	1976-Kobs, P.S. #14097 1977-Kobs, P.S. #14097 1979-Kobs, P.S. #14097 1989-Ayey, P.S. #30076	; Set post; 30" Lynn S46°W 20 Lnks; Survey L.2723, Pg.872 - Fnd Chis; Survey L.2811, Pg.745 - Same wit; Survey L.3074, Pg.521 - Same wit; LCRC L.4584, Pg.238 - Fnd chisel; Survey L.5831, Pg.305 - Same wit	eled cross in concrete pavemer s as 1976 Survey s as 1976 Survey ed cross in concrete pavement	nt.	
В.	1993 Kennedy Surveying	evidence found and/or method app , Inc Kennedy, P.S. #17623 - Fn of the Boulevard of 26 Mile Road	d chiseled cross that is locate	ed 1' West of the centerline of Van Dyke Road	
	Bug witness noint	s from the 1989 LCRC were found a	d they were used to recover ar	nd verify the found chiseled cross.	
	TWO MICHERS POINT	o ilom one iyoy pene nele i am	ACCEPTED B	Y THE MACOMB COUNTY	
			1	GROUP AS THE OFFICIAL	
			• · · · · · · · · · · · · · · · · · · ·		
				ER MICHIGAN PUBLIC ACT 345	
			OF 1990 AT	A MEETING HELD ON	
			12-15-9	3 .	
				a next	
				O COLUMN TO THE	
				INK J. DODECKER, PS, PE, CHAIRMAN	
Ç.	Description of monume	ent for corner and accessories est	ablished to perpetuate locating	the position of the corner:	
				2 By A Vancourant W	
	Act 345 #17623" i S79°E-36.35'-Set PK Na N27°E-87.87'-Set PK Na S86°W-35.31'-Set PK Na	und chiseled cross with a 3/4" x n a monument box. il & Remon. tag in South face Powill & Remon. tag above existing will & Remon. tag in North face Powill & Remon. tag in NW face Power.	er Pole tness in SE face Power Pole er Pole	minum cap stamped "Macomb County Monument MI	
	-	•		MICH. OF MICH.	
	The calented location	is accepted by me and is generall	v accepted by Professional Sur	veyors as the hest available cyclence of the	
	position of the or	idinal corner	1		
	bosicion of the or	TAINGT COTHET!		HUSTON KENNEDY	
	_ /			LAND	
	(Y/. 4)	// _A	10		
Sic	ned by		Date	17623	
		17621			
Su	rveyor's Michigan Licens	se No	FORM A	APPROVED BY MICHIGAR STARE COARD OF AND SUBVEYORS, JAN. 28, 1971	
				REVISED JAN., 1983	

· 40