## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in LENOX TOWNSHIP	1
MACOMB Located In: Corner Co	LIBER 9268 PAGE 9
1. Public Land Survey  T4N R14E  TR  TR  TR	12/27/1999 01:15:14 P.M. MACOMB COUNTY, MI CARMELLA SABAUGH, REG/DEEDS  SURVEY & TO THE POWER OF
2. Property Controlling S T R	WAR 1 7 2000  SECTION Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	<del></del>
I, ROBERT H. BIRKETT, in a field survey on JULY 10, 1999 do here requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention above were in conformance with regulations and rules therefore as remanual of survey instructions of the United States Department of the Internal Management or by a decree of a Court of Law and /or that the corner point 3, 4 and 5 above were in conformance with the rules of the Michigan Boar or by a Decree of a Court of Law; established, re-established, monument recovered, found as expressed below:	by certify that under 3 oned in lines 1 and 2 quired in the current erior, Bureau of Land 5 nts mentioned in lines 6 rd of Land Surveyors 7
NOTE: Not more than 2 corners, all in the same town and range, ma on this certificate.	ay be recorded 10 30 29 28 27 26 25 11 12 31 32 33 34 23 6 6 36 1
A. Description of original monument and accessories and/or subsequent restoration:  G-13 LENOX . 1817 W. PRESTON, GLO, SET WOOD POST  (a) 1961, MSHD, WITNESS RECORD RAILROAD SPIKE IN 26 MILE ROAD.  (b) 1992, M.C.R.C. WITNESS RECORD MONUMENTATION TYPE NOT INDICATED.  (c) 1982, W. SODERBERG # 17635, ½" RE-ROD IN MONUMENT BOX, L.C.R.C., L. 3403, P. 775 M.C.R.  (d) 1982, H. KOBS # 14097, FOUND ½" IRON BAR IN PAVEMENT, L.C.R.C., L. 3465, P. 173 M.C.R.  (e) 1988, G. WARD # 22445, FOUND ½" BAR IN MONUMENT BOX, L.C.R.C., L. 4546, P. 342 M.C.R.  (f) 1988, STEPHENS # 29252, FOUND BAR ½" IN MONUMENT BOX, SURVEY, L. 5969, P. 139 M.C.R.  (g) 1993, D. KING # 30085, ½" IRON IN MONUMENT BOX, L.C.R.C., L. 6586, P. 196 M.C.R.  (h) 1994, D. KING # 30085, ½" IRON IN MONUMENT BOX, SURVEY, L. 7430, P. 841 M.C.R.	
B. Description of corner evidence found and/or method applied in restored G-13 LENOX FOUND ½" IRON IN MONUMENT BOX .5" DEEP 1' SOU'N. (e 31.95') P.K. NAIL EAST FACE UTILITY POLE S.W. (e 156.34') SET P.K. DISC. NORTH FACE TRIPLE STEM ASH. N.W. (e 227.66') P.K. NAIL SOUTH FACE UTILITY POLE. N.W. (f 31.88') P.K. IN EAST FACE DETROIT EDISON POLE. N.W. (g, i 58.26') CHISELED X ON SOUTH RIM OF WATER GATE.	
G.L.O. (1817) - 40 CHAINS (2640') GLO (NONE)	TATION (199) - 2279.37'  PROFESSIONAL SURVEYOR NO. 41094  **TOPESSIONAL SURVEYOR NO. **TOPESSIONAL SURVEYOR SUR
C. Description of monument for comer and accessories established to perpetuate locating the position of the corner: G-13 LENOX. REMOVED ½" IRON AND SET A 3/4" IRON WITH A 2" DIAMETER ALUMINUM CAP STAMPED "MACOMB COUNTY MONUMENT, MI ACT 345, #41094, G-13" IN EXISTING MONUMENT BOX.	
AZ 355° 32.01' - SET REMON TAG ABOVE FOUND P.K. NAIL EAST FACE UTILITY POLE. AZ 75° 217.89' - SET REMON TAG ABOVE FOUND P.K. NAIL WEST FACE UTILITY POLE. AZ 255° 105.50' - FOUND P.K. NAIL SOUTH END 12" CMP. AZ 275° 227.68' - SET REMON TAG ABOVE FOUND P.K. SOUTH FACE UTILITY POLE. AZ 315° 58.32' FD. CH. "+" SOUTHEAST RIM WATER GATE.	
THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.	
Signed by Surveyor's Michigan License No. 41094	ER NOVEMBER 23, 1999

948

MACOUR COUNTY LENOX TOWNSHIP TOWN 4 NORTH, RANGE 14 EAST G-13

MORTH

SURVEY & RELUCE TATION

MAR 17 2000

SECTION

One of the state of th

100×25 ×15