LAND CORNER RECORDATION CERTIFICATE

For corners in	riling Requi	rement of Act /4	, Mich. P.A. 1	1970			É	De a e e e e e		6 .					
Macomb (County)	Located In:Biruce⊝T₩pCo		SURVEY & PENONUMENTATION												
1. Public Land Survey	ublic Land Survey						FEB 2 7 1997								
	T R T R						C	OM	MISS	ION	ļ				
Property Controlling In Section Miscellaneous Property in Sec.	S TR S TR S TR S TR				Re	gister	of De	eds S	tamp &	k File '	Num!	ber			
4. Lot No, Reco	rded Plat														
5. Private Claims				1	A E	3 C	D E	F	G H	I J	<u> </u>	L M			
				2 3	<u> </u>	5	-5-	— å	- j		+	- 1 -			
Huston K. Kennedy, in a field survey on 4/12, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,					1	8	- 8		15	11-11-11-11-11-11-11-11-11-11-11-11-11-		-12			
recovered, found as expressed be	elow:	abiististi, Te-estabiisije	u, monumented,	8		9	-20-		22_	23		-24			
NOTE: Not more than 2 comon this certificate.	ners, all in the same town and rang	ge, may be recorded		9			+		\vdash	++	+				
On this Certificate,				10	—3i		29	—28	27-	26		-2'5			
				12	3 <u>1</u>		32	 33	34	35-		-36			
A. Description of original mo	onument and accessories and/or	subsequent restorat	ion:	13	L				<u>L. </u>	11					
						ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 5-21-34									
B. Description of corner evid	dence found and/or method appli	ied in restoring or re	establishing co	rner:	W	LLIAM	E, SO	DERBE	RG, P.S.,	, CHAIF	MÁN				
THE STATE OF CONTRACTING	Inc Kennedy, PS #17623 - Fn to the East & West, which has #1 & 2 were used to recover a	s a dicuminous sur	race, and 22	reet E	ast	of t	he dr	iveway	for h	ouse #	1159	ne of 1.			
FIELD MEASUREMENTS B		nd verify the roca	crou of the L	ound 1	1/2"	iron	KOQ .	ın a M	onument	t Box.					
I-12 to I-13 GLO = 40	O chains or 2640.00 Ft., 2712 O chains or 2640.00 Ft., 2632	.08 Ft. (GPS-MEA) .82 Ft. (GPS-MEA)													
C. Description of monument	for corner and accessories estab	lished to perpetuate	locating the po	sition	of th	e cor	ner:								
S40°W 68.15' Set PK 8 Due South 30.26' Set S40°E 50.28' Set PK 8	1/2" Iron Rod with a 3/4" x : n a existing Monument Box & Remon Washer North face 42" PK & Remon Washer East face 46 & Remon Washer East face 40" (& Remon Washer East face Power	Oak 44° Oak Oak	diameter alum	inum c	cap :	stampe	ed "M	acomb	County	Monum	ient				
	accepted by me and is general						best	ฐ์ ห ใั∈กoo	OF MA ENNEC FEQSIC	OY S	No of the second	the			
Signed by			Date/2	2-12	? - ?	76			17023		B	Glegge.			
Surveyor's Michigan License N	vo176QВ					<u> </u>		PROF	ESSION	LESUS	C. C	- 			

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1975
REVISED JAN., 1983
REVISED OCT., 1995

620