SURVEY & RF NUMENTATION

SURVEY & REMONUMENTATION

APR 2 8 1998

LAND CORNER RECORDATION CERTIFICATE

JAN 2 1 1998

_, Recorded Plat

4. Lot No.

SECTION	
REGISTER'S OFFICE	

MANISTEE COUNTY JUN 1 0 1997

CDEFGHIJKLM

3

10

15

22

27

2

11

14

23

26

ī

12

13

24

25

36

MEborah Dix

4

9

16

21

28

33

Register of Deeds Stamp & File Number

5

8

17

20

29

32

2

3

5

6 18

7

8

0

10

11

12 31

6

7

19

30

	——————————————————————————————————————	Filing Requirement of Act 74, Mich. P.A. 19			
or corners in SE(Manistee (County)	CTION Located In:	Corner Code #			
. Public Land Survey	T_21N_R_16W TR T_21N_R_15W TR	M-13 SMO480 A 13			
. Property Controlling in Section	STR STR		Reg		
. Miscellaneous S Property in Sec.	TR STR		<u></u>		

5. Private Claims , in a field survey on <u>April</u> L Richard L. Havs do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recoverred, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: SOUTHEAST CORNER OF SECTION 36. T21N-R16W

1837: G.L.O Post

1945: Sam Walker Survey "American Box Board Co.

No Witnesses; Monument set by Walker, is 12" Yellow Pine N-50 1/2-W 3.57 lks (1)

14" Yellow Pine S-72°-W 4.30 lks (2) S-55°-E 68.15' from the Griffin Monument.

1971: Robert Griffin #13584, LCRC #73-35. 1918: Theodore Norlin Survey Peg by old Stake. Established Corner from Norlin Notes, and 6" White Oak S-30°-W 70.8'(3) Witness Tree to the Recovered True Location. W-W Section 31 NORTH 2592' (4) 5" Red Pine N-05°-E 62.03'(5) 5" Red Pine N-65°-W 104.27'(6)

N-29*-W 5" Red Pine 57.08' (7) 4" Dia. Iron Pipe in Concrete

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SOUTHEAST CORNER OF SECTION 36, T21N-R16W

April 1997: Found a 5" Square Concrete USFS Monument, 5' in length with a 3" Stamped Brass Disc. Condition of the Witnesses are as follows:

12" Yellow Pine 14" Yellow Pine N-50 1/2-W 3.57 lks (1) GONE S-72*-W 4.30 lks (2) GONE 6" White Oak S-30*-W 70.8' (3) GONE 2592' (4) DID NOT CHECK 62.03' (5) FOUND W-% Section 31 NORTH 5" Red Pine N-05*-R 5" Red Pine 104.27' (6) FOUND N-65*-W N-29*-W 57.08' (7) FOUND 5" Red Pine S-55*-R 68.15' (8) FOUND 4" Dia. Iron Pipe in Concrete

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Description of intertainment to sent and the sent and the sent and faithful perpetuation of the position of the Original Corner.

10" Red Pine N-05°-E 62.03' (5)

4" Dia. Iron Pipe in Concrete S-55°-E 68.15' (8)

2" Dead Pine N-29°-W 57.05' (7)

S-40 -W Power Pole 27.774

South of the Centerline of County Line Grand
ratified by the Manistae County Peer Grand Corner is 12' So according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54.261

et. seg.). Date of Peer Review: The state of the s

Date ___ Slaned by

Surveyor's Michigan License No. 25847

WAID LAKE 24847

L EAYS

LAND

A EVEYOR