

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>21</u> N. <u>0</u> R. <u>16</u> <u>0</u>	<u>K-11; L-11; M-9; M-11</u>
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER _____

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on April 11, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C. (continued)

M-11			
Found concrete monument			
20" W. Oak	S14°E		39.14
8" B. Oak	S65°E		43.25
16" W. Pine	N35°E		63.84
1"x13" pipe	N89°E		60.5

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:


- K-11 Accepted concrete monument by RLS Sam Walker as recovered, witnessed and recorded by RLS Ken Ross.
- L-11 Accepted 1" pipe by RLS Sam Walker as recovered, witnessed, and recorded by RLS Ken Ross.
- M-9 Accepted 3/4" pipe as recovered, witnesses and recorded by RLS Ken Ross.
- M-11 Accepted concrete monument by RLS Sam Walker, as recovered, witnessed and recorded by RLS Ken Ross.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11	L-11	M-9
Found Concrete monument		
1" pipe N09°40'E 67.70	Found 1" pipe	Found 3/4" pipe
4" B. Oak N50°E 33.81	16" Pine N20°W 66.01	30" Oak S40°E 36.52
6" Pine N70°W 17.30	CCC post N10°W 46.2	8" Oak Due W 26.92
84' S of N edge of pine plant	8" W. Pine N40°E 58.32	10" Oak N10°E 53.29

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ STRONACH TOWNSHIP
MANISTEE COUNTY