VICE COLV

. 38

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement For corners in	nt of Act 74, Mich. F	P.A. 1970		
Manistee (County)	Located in:	Corner Code #	REGISTER'S OF	INIY
1. Public Land Survey	T_21N R_17W T R T R T_2/N R_16W	M-12 <u>East ¼ Cor.</u> <u>Sec. 36</u> <u>A-12</u>) E. Filun	JUN 29 19 REGISTER OF I	<u> </u>
2. Property Controlling S	T R T R T R _ Plat		Register of Deeds Stamp & File Number	
I, Anthony M. Slawinski, in a funder requirements of P.A. 74, Michigar above were in conformance with regular survey instructions of the United States by a decree of a Court of Law and /or were in conformance with the rules of Court of Law; established, re-established	n P.A. of 1970, the cornicons and rules therefore Department of the Inte that the corner points rithe Michigan Board of Id, monumented, recoverall in the same town a	as required in the current manual of rior, Bureau of Land Management or mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree of a ed, found as expressed below:	A B C D B F G 1 2 6 5 4 3 4 7 8 9 10 30 29 28	H I J K L M - 3. 2 1 - 10 11 12 - 15 14 13 - 22 23 24 - 27 26 25
 2. Beech 8" N 54 ½° W 46 links B. Description of corner evidence reestablishing corner: Information Referenced: 	(Gone)	applied in restoring or	12 31 32 33	34 35 36
Michigan Department of Transportar (1952) Found ¾" pipe in monument 1'E C.L. US31, 2'N of Fe. Line E-W 3. S 85° E 33.58' Cor. Fe. Post 4. S 83° E 53.07' 4" Elm 5. S 75° W 53.82' Power Pole 6. N 60° W 44.60' Fe. Post	box	Survey Certificate by Zwar (1996) Survey Certificate by Ross (1974) iron in mon. box 7. S 34° E 33.19′ Fen. Post 5. S 72°W 53.68′ Power Pole 8. S 37° W 125.23′ Apple Tre	4) (Gone) (Gone)	A. 345 of 1990, Act, MCL 54.261
L.C.R.C by Fluharty (1974) fd. %" pipe in mon. box in C.L. US- 9. East 33.43' F.P. 10. N 45° E 53.51' F.P. 4N Cor. 5. S 70° W 53.72' P.P.	31 (Gone) (Gone) (Gone)	U.S 31 Right of Way Map		the Manistee Conviction to P., the Remonuncial Confession of Table 2, 1998
On May 20,1998, I, Anthony Slawin the approximate center line of U.S.		nmarche, found a ¾" iron pipe wit	thin a monument box	(/)
C. Description of monument for cor On May 20, 1998, I installed a Man mentioned ¾" iron pipe, as a carefu	istee County Monume	ent, within a monument box, in th	e exact location as the above	oduniy pian go the State Peer Review
11. S 71° W 52.88′ Power Pole, 12. S 62° W 140.80′ Northeast C 4. S 74° E 53.05′ 5″ Elm, 60D s 13. N 60° E 73.59′ 4″ Fence Post	60D spike in the Nort Corner of House at fou pike in the North side	h side undation		Comer $\mathcal{M} = \frac{8}{2}$, as according to the constant (being the constant). Date of Petron 1
Note: Corner is in the Centerline of 25, T21N, R17W.	Highway U.S 31. N	North 2646.30 feet to the Souther	ast corner of Section	888
Signed by Guthony m.		SLAWINSKI SURVEYOR NO.	Z Date 6-1-	98
Surveyor's Michigan License No. 13	<u>597</u>	FORM ARROYED BY MICHIG	GAN STATE BOARD OF PROFESSIONAL S	SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT 1995