DEC 2 9 1096 ESCHELLER ST.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Manistee Located In:	Corner Code #	REGISTER'S OF MANISTEE COL	JNTY
1. Public Land Survey	East ¼ Corner Section 11	97-392 at OCT 17 199 NEborah Six	37
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R		REGISTER OF DI	,
4. Lot No, Recorded Plat 5. Private Claims		A B C D E F G B	I J K L M
I, Anthony M. Slawinski, in a field survey on under requirements of P.A. 74, Michigan P.A. of 1970, the above were in conformance with regulations and rules there survey instructions of the United States Department of the by a decree of a Court of Law and for that the corner point were in conformance with the rules of the Michigan Board Court of Law; established, re-established, monumented, received.	July 29, 19 97 do hereby state that corner points mentioned in lines 1 and 2 afore as required in the current manual of Interior, Bureau of Land Management or ints mentioned in lines 3, 4 and 5 above to of Land Surveyors or by a Decree of a	1 2 6 5 4 3 3 4 7 8 9 1 1 5 5 6 18 17 16 11	51415
NOTE: Not more than 2 corners, all in the same tow on this certificate.	wn and range, may be recorded	8 -19 -20 21 22	22324
A. Description of original monument and accessories K-04 East ¼ Corner of Section 11, T21N., R17W.	s and/or subsequent restoration:	1 30 29 28 27	26 -25
Set by John Brink in 1837		13 3 3 3 3 4	35 36
Set West Section Post, Section 12 (T21N., R17W.) 1. Beech 12" N 38° E 31 links (Gone) 2. Hemlock 18" S 58° W 30 links (Gone) B. Description of corner evidence found and/or met	thad applied in rectaring or reactablishi	ing corner!	Group 1990, 54.261
B. Description of corner evidence found and/or met K-04 East ¼ Corner of Section 11, T21N., R17W.	ation applied in restoring of reestablish	ing comer.	ू ठ दू
Found ¾" Iron Pipe by Slawinski (1955) 3. NE 42.78' Power Pole (Gone) 4. SE 42.73' Power Pole (Gone) 5. SW 32.13' Power Pole 6. NW 40.69' Power Pole	Also referenced: GLO Field Notes by John Brink (183 Slawinski Field Notes (1984)	(7) Book 1, Page 429	ne Manistee County Peursuant to P.A. 345 Remonument Act, MC
	Engelwood Plat (5-23-1881), Vol. 2	of Plats, Page 40	e Manis rsuant Remonu
On July 29, 1997 a %" Iron Pipe was found by Anthony Slawinski & Abonmarche. Below the pipe a chiseled "X" in concrete was found.	Mark S. Tyson & Co.'s Addition(9-2 Liber 5, Pages 218 & 219	:-1867),	ratified by the adopted posturely and survey and
C. Description of monument for corner and accessor K-04 East ¼ Corner of Section 11, T21N., R17W.	ries established to perpetuate locating	the position of the corner:	county plan give State
On July 29, 1997, I installed a Manistee County Mor Iron Pipe and chiseled "X" as a careful and faithful re	nument, within a monument box, in th e-establishment of the position of the c	e exact location of the above priginal corner, and witnessed	/4 = = -
5. S 55° W 32.03' Power Pole (Spike in the North 6. N 56° W 40.75' Power Pole (Spike in the North 7. N 70° E 52.00' 24" Maple (Spike in the South 8. S 54° E 47.23' 14" Maple (Spike in the North This corner was set at the intersection of the center	theast side) heast Side) least side) heast side)	ANTHONY ANTHONY SLAWINSKI SURVEYOR	Comer & – according to as amended, et. seg.). Da
Signed by Gruttrong m. Slaw	ushi	13597 ET LAND SUPLED SU	97

FORM APPROVED BY MICHIGAN STATE BOARD OF .

Signed by Guttony m.

Surveyor's Michigan License No. 13597