SECHOR

Signed by Guthany m. Surveyor's Michigan License No. 13597

LAND CORNER RECORDATION CERTIFICATE

Filing Requirem For corners in	ent of Act 74, Mich	i. P.A. 1970	
Manistee (County)	Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY
1. Public Land Survey	T <u>21N</u> R <u>17W</u> T R T R	S.E. Sec. Cor. Sec. 25	18 345 at 9:30am JUN 29 1998
2. Property Controlling S_	TR TR TR		REGISTER OF DEEDS
in Section S_ 3. Miscellaneous S_ Property in Sec. S_ 4. Lot No, Recorde	TR TR		Register of Deeds Stamp & File Number
5. Private Claims I, Anthony M. Slawinski, in a under requirements of P.A. 74, Michinabove were in conformance with regusurvey instructions of the United Starby a decree of a Court of Law and / were in conformance with the rules Court of Law; established, re-established.	a field survey on M gan P.A. of 1970, the culations and rules therefites Department of the lifer that the corner point of the Michigan Board shed, monumented, record	Nav 20, 19 98 do hereby state that corner points mentioned in lines 1 and 2 ore as required in the current manual of the nation of Land Management or its mentioned in lines 3, 4 and 5 above of Land Surveyors or by a Decree of a	A B C D E F G H I J K L M 2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 12 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16
A. Description of original monun	ment and accessories	and/or subsequent restoration:	6 18 17 16 15 14 13
Set by John Brink in 1837 1. Hemlock 11" S 56½° W 20 2. Sugar 10" N 62° W 34 link			10 30 29 28 27 26 25
B. Description of corner evidence reestablishing corner: Information Referenced: County Survey Notes by E.W.M. 3. N 53¼° W 53½′ Oak (Gone 4. N 57 E 70½′ Oak (Gone Michigan Department of Transport (1952) Found ½″ Rerod in monuting	(1893) e) e) rtation Map	od applied in restoring or	12 31 32 33 34 35 36
C.L. of US-31 & C.L. Fox Farm R 5. S 60° E 61.68' Power Pole		Survey Certificate by Ross (19	
6. \$ 35° E 54.78′ N.E. Cor. E 1 7. \$ 30° W 53.72′ G. Post 8. \$ 30°W 54.91′ N.E. Cor. W	(Gone)	Survey Certificate by Slawinski Survey certificate by Slawinski	
Michigan Department of Transportd.5/8" iron in Pavement (1952)	rtation Map	U.S 31 Right of Way Map	unity Pee. 1. 345 of lot, MCL.
9. S 53° E 55.80′ Maple 10. N 64° E 32.37′ S.W. Cor. 11. N 68° W 75.58′ 3″ Maple	(Gone) Hdwl. (Gone) (Gone)	Survey Certificate by Slawinsk	a a g a l i
•		Abonmarche, found a ½" iron bar w	vithin a monument box.
•		es established to perpetuate locating	7 ≥€ ₹ £
On May 20, 1998, I installed a Nabove mentioned ½" iron bar, as witnessed by:	Manistee County Mone a careful and faithfu	ument, within a monument box, in I re-establishment of the position of	r the original corner, and
5. S 60° E 61.68′ Power Pole, 12. N 54° W 90.64′ Power Po 13. S 82° W 112.79′ Power P 14. N 42° E 94.60′ 12″ Lomba	le, 60D spike in the Nole, spike with tag in	North side South side	to the county bd, (being the Bate of Rear B
Note: Corner is in the Centerline North 2652.00 feet to the	inter sections of Fox East ¼ Corner of Se	Farm Road and Highway II S. 31. oction 25, T21N, R1 WOF MIC, ANTHONY M. SLAWINSKI SURVEYOR	∑ iniger

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14,1976
REVISED JAN., 1983