SURVEY & REMONUMENTATION

DEC (19 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in MANISTEE Located In (County)	n: Corner Code #		REGISTER'S OFFICE MANISTEE COUNTY いったられる大石にある。						
1. Public Land Survey T 22 N F T 22 N F T 22 N F T 7	R 13 W A-7		a	Dr.	UG 1 borci IISTER	2 19! <u>Uh</u>	99 .u.	-	
3. Miscellaneous S T R Property in Sec. S T R		Regi	ster of	Deeds	s Stam	p & Fil	e Numl	oer 	
Lot No, Recorded Plat Private Claims	·	17	A B (C D	E F	э н	ΙJΚ	L M	
		2	-6	5	4	3	2	1	
I, Sammy S. Barnett, In a field survey on July 7th 19 99, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			7	8	9	10	11	12	
			18	17	16	15	14	13	
		8 8	19	20	21	22	23	24	
NOTE: Not more than 4 corners, all in trecorded on this certificate.	the same town and range, may be	10	30	29	28	27	26	25	
·		12	31	32	33	34	35	36	
A Description of original monument and accessories and/or subsequent restoration: M - 7 Corner common to sections 13 £ 24, T22N, R14W £ sections 18 £ 19 T22N, R13W 1837 GLO survey by John Brink, set post									
1909 Survey by Fargo Eng. Co. fd R.R. iron 1990 survey by R. Mitchell, Mon. not given, no witnesses given. 6 both U.S. Witnesses 7 W. Pine 25" N9W 9 lks (5.94') 8 W. Pine 28" N39 1/2 W 23 lks (15.18')									
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M - 7 Corner common to sections 13 & 24, T22N, R14W & sections 18 & 19 T22N, R13W On July 7th 1999, I found the 5" sq. con. mon. set by R. Griffin, stamped to identify the corner, the condition of the witnesses are as follows Gone # 1, # 2, # 3, # 4, # 5, # 6 & # 11 found in good condition # 7, # 8, # 9 & # 10. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M - 7 Corner common to sections 13 & 24, T22N, P14W & sections 19 P									
M - 7 Corner common to sections 13 & 24 On July 7th 1999 I accepted this 5" sq. the position of the original corner, & f # 7 W. Oak 14" S57E 53.14' fd. 90d spike # 8 R. Oak 14" N33E 62.56' fd. 90d spike # 9 Haple 12" S15W 53.63' fd. 90d spike # 10 W. Oak 10" S52W 73.58' fd. 90d spil # 12 carsonite post South 33'	con. mon as a substantial marker and a took the following witnesses. e in SW side e in SE side	jine po R13W as a c:	osition (of the c	corner:	perpet	cuation	of	
as amended, (issing left.seg.). Date of Pe	ratified by the Manistee County Peer ounty plan submine seement in P.A. 345 of the Manistee County Peer of the Manistee County Peer out to P.A. 345 of the Manistee County Peer of the Manistee County	1990, 61,261		Tipe No.	BA PROF SU	MMY RNET ESSION RVEYO No. 16923	T)	TO	
Surveyor's Michigan License No. P S #		<i>-</i>					•		