## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

		; · ·	
FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	REGISTER'S OFFICE
1. PUBLIC LAND SURVEY	22N N. 13VV E. S., R. W.	M2   :	#94-249 AT 10:05 A
2. PROPERTY CONTROLL- ING IN SECTION——	,T N. E. W.	SURVEY &	JUN 1 5 1994
3. MISCELLANEOUS PROPERTY IN SECTION	p=1	EMONUMENTATION	REGISTER OF DEEDS
4. LOT NO, RECO		JUL 1 4 1994	
ļ		COMMING	
5. PRIVATE CLAIMS		COMMISSION	REG STER OF DEEDS STAMP AND FILING NUMBER
I, Patrick R. Leemon the corner points mentioned in field survey on March 30 restored as expressed below and of survey instructions of the Un court of law. Furthermore, 19	lines 1 and 2 above (iden 1994, established d in conformance with regu- lited States Department of that the corner points me ound, recovered, restored, es	tified with circles on index, re-established, monumente lations and rules therefore as the Interior, Bureau of Land lentioned in lines 3,4 and 5 a stablished or re-established	code diagram - over) were, in a d, re-monumented, recovered or sequired in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in con-
A. Description of original monum	ment and accessories and/	or subsequent restoration:	Group 7.280,
1/4 corner common to set 1837 survey by John Brink Set Wood Post #1 Y.Pine 14 S64W 33 links #2 W.Oak 10 N28W 27 links 1985 survey by Ed McCombs #1 Fd. conc. monu. by Griffin #10 Oak 25 N58E 65.61 feet Also used wit's. 5, 9 & 7	1977 survey by Jerry W Fd. conc. monu. by Griffi #7 R.Pine 10 S65W 64.9 #8 J.Pine (?) 8 N75E 66 #5 J.Pine (?) 8 N75E 66 #9 Oak 6 S70E 52.10 fe 1908 survey by E.H. Ba Fd. one GLO bearing tre #3 W.Oak 6 S80W 40 lir	in Est by Prop. Meas 28 feet SE13 & NE1. Set 1 26 feet long conc. monu. v 33 feet #6 R.Pine 6 N77E et #6 P.Post 7 East 1 iird #7 R.Pine 5 S64W e #8 W.Pine N22W 6	obert A. Griffin s. between a 5" sq.x 60" w/brass cap. 62.35 feet5 feet 64.98 62.64 feet
B. Description of corner evidence	#4 Y.Pine Stp. 18 S27W ce found and/or method app		ishing corner: Ag the
the centerline of the N-S ro through 10 are in good com- Page 220 by Griffin docume survey by Clinton Cole #17 stream meanders greatly no conflicting information the	ad. Witnesses 1 through 4 dition. Witness 8 is a W.P ents the history of this corn 615. The GLO calls do not There is a lack of occupationat would lead to another logarithful reastablishment of faithful reastablishment of	w/ brass cap by Griffin 22 feet and 6 are gone. Witnesses ine and witness 5 is a R.Pine er. This monument was used aid in determining this location to assist in recovery and I ocation. I therefore accept the the position of the original costablished to perpetuate locations.	the could find e found because of the could find the could find e found because of the could find the coul
<u>.</u>		•	ner ordin
C. Description of monument for  1/4 corner common to see  Monu. The 5" sq. by 60" lo.  Witnesses:	ctions 1 of T22N R13W and concrete monu. with 3"	nd section 6 of T22N R12W brass disk was left in place.	S 25 25 26 25 25 25 25 25 25 25 25 25 25 25 25 25
R.Pine 5 S21W 79.59 feet R.Pine 9 N77E 62.33 feet ( R.Pine 8 S64W 64.98 feet ( W.Pine 8 N22W 62.77 feet R.Oak 26 N58E 65.53 feet	#7) (#8)		E OF MICHIGA
CICNED BY CHILL	24	DATE April 20	PATRICK R.
SIGNED BY Fabrick CR	24501		型 [4] EXHID 手作器
SURVEYOR'S MICHIGAN REGIS	STRATION NO. 31595		SURVEYOR NO.
FOR STATE AND UNITED STA		, 5.75	31595 A H D 5 W
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	MICHIGAN REGISTERED LAN	DATE	(SEAL)
	•		, years

SURVEYOR'S MICHIGAN REGISTRATION NO.