LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 COMMISSION

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
I. PUBLIC LAND SURVEY	22N N. 13W E.	M7	REGISTER'S OFFICE
	N. E. S., R. W.		#94-250 AT 10:08 A1
			Penny L. A. Renna
3. MISCELLANEOUS PROPERTY IN SECTION	_ , T S., R W.		REGISTER OF DEEDS
4. LOT NO, RECO	ORDED PLAT		_ .
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
1			FILING NUMBER
the corner points mentioned i field survey on March 30 restored as expressed below a of survey instructions of the L court of law. Furthermore. 19 , formance with the rules of the law: A. Description of original mon Section Cor. com. to see 1837 survey by John Brink Set Wood Post #1 S.Maple 10 S33W 55 links #2 Elm 10 N54W 52 links B. Description of corner evides I found the 5" square by 3	n lines 1 and 2 above (iden 1994, established and in conformance with regu United States Department of the corner points me found, recovered, restored, et Michigan State Board of Regument and accessories and/c's. 13 and 24 of T22N R13 1909 survey by Fargo Eng Fd. wit. #2 & set 1.P. w/ lime #3 S.Maple 12 S24W 29 lime #4 Hemlock 10 S75 3/4 E set 1.P. w/ lime Set a spike from Fargo notes No witnesses are mentioned.	tified with circles on inc., re-established, monumer lations and rules therefore the Interior, Bureau of Lacentioned in lines 3, 4 and stablished or re-established or re-established or subsequent restoration. W and sec's. 18 and 19 1976 survey by Robert Are Foldhe 10" spike by it with a 5" square	of T22N R12W A. Griffin #13584 (Cole & replaced by 36" long conc. DW 154 1581 A. Griffin #13584 (Cole & replaced by 36" long conc. DW 154 1581 TOWN
witnesses 6 through 8 are monument and is recorded location. There is a lack of information that would leathed did not dispute this location reestablishment of	in good condition. A 1990 of in Liber 2 Page 170. The of good occupation to assist d to another location. I talke ation. I therefore accept the the original corner.	survey by Clinton Cole us GLO calls do not aid in de in recovery and I could fired to the property owner of found monument as a cal	sed this etermining this and no conflicting of the house and areful and
C. Description of monument for	or corner and accessories e	stablished to perpetuate 1	ocating the position of the
Monu. The 5" sq. by 36" l Witnesses:	feet t	brass disk was left in plac	
SIGNED BY Gatrick Co	Sugar_	DATE -Apri	PATRICK R.
SURVEYOR'S MICHIGAN REG	ISTRATION NO. — 31598		SHALLYE FOR NO.
FOR STATE AND UNITED STA			31595
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	CAND STATE
APPROVED AND SIGNED BY_		DATE -	(SEAL)
SURVEYOR'S MICHIGAN REGI	STRATION NO	· · ·	

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971

Form No. MLM735