

MAY 1 6 1097

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	n	riiliig nequile	ment of Act 14, mich. 1.A. 1	3.0	
MANISTEE		Located In:	Corner Code ##	REGISTER'S OFFICE	
C (C	County			MANISTEE COUNTY	
		T 22 N R 16 W	(Mine)	# 96-305 AT 10:20 A.M.	
1. Public La	ind Survey	132N 8 12M	A-08	JUL 1 7 1996	
		T R	7. 0	$\Omega \rightarrow \Omega$	
		T R		Terray a Pepera	
2. Property	Controlling	S T R		REGISTER OF DEEDS	
in Section	· ·	S T R			
3. Miscellar		S T R		Register of Deeds Stamp & File Number	
Property		S T R		Tregister of Deeds oftening a File Hamber	
•					
4. Lot No	, Re	corded Plat		— A B C D E F G H I J K L M	
5. Private C	laims				
		•		2 - 6 - 4 - 5 - 4 - 4 - 3 - 1 - 2 - 4 - 1 - 1	
-	-			³ <del>├ ├ ├ ├ ├ ├ ├ ├ ├ ├ ├ ├ </del>	
C C 1	D <b>L L</b>	Mare	6 36	⁴	
1, Sammy S. Barnett , in a field survey on May 6 , 1996 , 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5					
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					
current manual of survey instructions of the United States Department of the Interior, Bureau of Land					
Management o	or by a decree of a	Court of Law and/or that the corne	r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a	8 19 20 21 22 23 24	
Court of Law:	contormance with : established, re-	the rules of the Michigan Board o -established, monumented, re-ri	ncand Surveyors or by a Decree of a nonumented, recovered, found as	┇	
expressed bel		• • • • • • • • • • • • • • • • • • • •		10 30 29 28 27 26 25	
NOTE: Not	more than 4 co	rners, all in the same town an	d range, may be recorded	11	
on ti	his certificate.			12 32 33 34 35 36	
•				13	
A. Description of original monument and accessories and/or subsequent restoration:					
M-08 East	M-08 East 1/4 for Section 24, T22N, R16W, on the Township Line				
JOHN 1	BRINK 1837	,			
	1,143	, G.L.O., boundary survey		N63½°E 331ks.(21.78')	
	Wood Post		#5 W. Pine Stump	14" N46°E 381ks.(25.08')	
		40°W 461ks.(30.36')	Larry Carechhacha	er, RLS#18990, 1975	
#2 1	Beech 9" N	34°N 361ks.(23.76')		/RLS cap @ single proportion distance	
Farc	go Eng. Co., N	o Date		3°W 111.00' #9 R. Pine 8" N37°W	
The second secon	nd very 01d Fe		#7 Wild Cherry 12	" N71°E 61.08' 123.36'	
#3 V	White Pine Stu	mp 14" N47 $\frac{1}{2}$ °W 1021ks.(67.	.32') #8 Choke Cherry 8 pplied in restoring or reestablis	" SO6°W 71.77'	
B. Descripti	on of corner evi	dence found and/or method a	pplied in restoring or reestablis	1991 surery by	
M-08 East	: 1/4 corner fo	or Section 24, T22N, R16W.	on the Township Line	B. Jenema same	
		<del></del>		witnesses as Larry	
	On May 6, 1996	5, I found a 5/8" Re-rod wi	th a RLS cap #18990, 24" lor	ng, set by Gerschbacher, this	
				dence to dispute this location	
• ,	for the 1/4 corner. Note; Measured 38.32' North to Indian Reserve Corner, Brink had 37.62'.				
Also found RLS cap Re-rod by B. Jenema, 27.81' South of corner, next to brake cam. Condition of recorded witnesses are;					
Cond	lition of recor	rded witnesses are;	a M &		
#1	Gone	#6 Found in a	Comer 17 - 20	ratified by the Manistee County Peer Gro	
	Gone	#7 Found in a	and conditions amount in	rained by the Manistee County Peer Gro	
		_	as amended, (bell)	J DR SING SURMY and Domonium and All trop at a	
#4	Gone	#9 Found in p	हाः ३०५ / ै Uशाई Of l oor condition	Ger Review: JUL 2 1996  Authory M Slaunching the position of the corner:	
#5	Gone	·		grottom m Il	
C. Description	on of manument	t for corner and accessories e	stablished to perpetuate locating	ng the position of the corner:	
				•	
M-08 East	. 1/4 corner fo	or Section 24, T22N, R16W,	on the Township Line		
		MI D I A M			
helo	r rebraceo 2/6	or ke-rod, in the exact loc	ation, with a Standard Manis	stee County monument, set 1 foot	
corn		and is accepted as a carer	ui and faithful reestablish	ment of the position of the original	
2017	1011			The state of the s	
(0B#	#6) Power Pol	e : 5 43° W - 11,80°C16n n	ail w/ shiner in SE side of	OF MICAN	
			spike in NE side of tree)	\$ 6 J	
•	Red Pine		Od spike in NE side of tree)	SAMMYS. *	
		ed Re-rod · 1/2" South	27.81'	PROFESSIONAL	
	P			SURVEYOR ON No.	
Signed by	Samo	& Harnet	Date 6-2	6-96 12 No.	
- Company and a second	iobinos Lisara	No 11.422		16923	
Signed by Sammy Garnt Date 6-26-96 No.  Surveyor's Michigan License No. 16923  FORM APPROVED BY MICHIGAN BY 11 THE APPROVED BY MICHIGAN BY 11 THE BARD OF TAND SURVEYOR. JAN. 28, 197  FORM APPROVED BY MICHIGAN BY 11 THE BARD OF TAND SURVEYOR. JAN. 28, 197  FORM APPROVED BY MICHIGAN BY 11 THE BARD OF TAND SURVEYOR. JAN. 28, 197					
REVISED JAH., 198					