SURVEY & REMONUMENTATION

DEC 1 = 1999

SECTION

or corners in

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Manistee Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY
. Public Land Survey T 22N R 15\ T 22N R 14 T R T R	W A-06	99-331 at 4:25pm SEP 29 1999 Deborah Dix REGISTER OF DEEDS
E. Property Controlling         S T R           in Section         S T R           E. Miscellaneous         S T R           Property in Sec.         S T R		Register of Deeds Stamp & File Number ABCDEFGHIJKLM
Lot No, Recorded Plat D. Private Claims		3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
, <u>Bruce J. Jenema</u> , in a field sun nereby state that under requirements of P.A. 74, Michigan P mines 1 and 2 above were in conformance with regulations are manual of survey instructions of the United States Dep management or by a decree of a Court of Law and /or that and 5 above were in conformance with the rules of the M Decree of a Court of Law; established, reestablished, more pelow:	A. of 1970, the corner points mentioned in and rules therefore as required in the current partment of the Interior, Bureau of Land the corner points mentioned in lines 3, 4 lichigan Board of Land Surveyors or by a	4 - 7 - 8 - 9 - 10 - 11 - 12 - 15 - 14 - 13 - 7 - 16 - 15 - 14 - 13 - 7 - 8 - 19 - 20 - 21 - 22 - 23 - 24 - 9 - 10 - 30 - 29 - 28 - 27 - 26 - 25
NOTE: Not more than 2 corners, all in the same to on this certificate.	town and range, may be recorded	11 12 -31 -32 -33 -34 -35 -36 -36
<ul> <li>A. Description of original monument and access subsequent restoration:</li> <li>M-06 T22N R15W (E ¼ corner Section 13) Cor 1837 J. Brink, D.S. GLO Set Post 1.) 9" Beech S37 1/2°W 29 links (19.14') 2.) 14" Beech N26°W 44 links (29.04')</li> <li>1914 J.H. Millard, C.S. Rec. C.S. Book B, pages 194 &amp; 195 Found stake &amp; government bearing trees 3.) 12" Sugar N58°W 17 links (11.22')</li> <li>1995 B.J. Jenema, P.S. Unrecorded survey Job #95239 Found 1 1/4" O.D. iron pipe</li> </ul>		6d Nail SE side
<ul> <li>B. Description of corner evidence found and/o</li> <li>On April 29, 1999, I found a 1 1/4" O.D. iron pip No conflicting evidence of other corners existing</li> </ul>	e hooked at the base and no lime found	1, 82,00
1.), 2.), 3.), 5.) & 6.) are now extinct. 4.) 12" Hard Maple S62°W 71.77' Now stump		AL PROPERTY.
C. Description of monument for corner and acc	essories established to perpetuate lo	ocating the position of the corner:
On July 14,1999, I placed a standard Manistee best available evidence of the location of the ori	County Monument in the exact position or iginal corner and witnessed by:	of the above 1 1/4" O.D. iron and is accepted as the
4.) 12" Hard Maple S62°W 71.77' 16-D Nail 8.) P.pole N10°E 124.91' Set 60-D spike W. s 10.) 12" B. Locust S90°W 60.48' South 60-D	ide 9.) 14" Maple S	se Block foundation N42°W 163.64' 85°E 51.45' Set 60-D spike S. side
Signed by Brush Jenema	Date 9	16-99
Surveyor's Michigan License No. 25850	EVDM VDDDUNEU DA M	ICHIGAN STATE ROARD OF PROFESSIONAL SURVEYORS