LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. P.A. 1970.

_			•				
	rners in MANISTEE (County)	Located In:	Corner Code ≠	<i>#</i>	MANISTE	R'S OFFICE E COUNTY	
I. Pul	blic Land Survey	T 23 N R 15 W	M-8		#40.5	84 AT 11:12 9 1995	A.M.
		T 231/ R /4W	A-8 V		Kenny A. REGISTER	Repera OF DEEDS	
	operty Controlling Section	S T R S T R		_		O. DELDO	
	scellaneous operty in Sec.	S T R S T R		Registe	er of Deeds Stan	p & File Numbe	r
. Loi	t No , F	Recorded Plat			ARCDE	: вылк	LM
							ŢÌ
				3			
Kenn	eth Ross	, in a field survey on June 28		9 95 5		1011	
current Manage above v Court co express	manual of survey instrument or by a decree of were in conformance wing Law; established, a sed below:	n conformance with regulations and uctions of the United States Departra Court of Law and/or that the corner th the rules of the Michigan Board of re-established, monumented, re-m	nent of the Interior, Bu points mentioned in lir Land Surveyors or by onumented, recovere	reau of Land nes 3, 4 and 5 a Decree of a d, found as	30 29 2	3 - 27 - 26	24- •
	on this certificate.			12 13	31323	33435	36
		monument and accessories and	or subsequent rest	oration:			
M -# 8	East 1/4 Corner	for Section 24, T23N,R15W.		L. M. Gerschbach	ser 1974		
	James L. Hingbie Used 18" Hemlock			Found RR. Spike round head bolt.	6" below road a	surface, Raised	with
	Set Stake (east	1900, Co. Sur. Book 'B' of fence post) 5 70° W 321k(21.12')	P 18+19	#3 Pin cherry 6	<u>75</u> N 65º E 51.0	.37'	ı
		evidence found and/or method a	pplied in restoring o	#4 Poplar 4" or reestablishing co	rner:		
1-8		or Section 24, T23N,R15W.				•	
•	evidence to disbu	1995, I found a 6" round bolute this location, measured Record Distance of 2612.28 f	a distance of 259	e in center-line of the state o	of Big Four Roa Southeast corne	d, found no r òf Section 2	4,
	Condition of Reco	orded witnesses is; #1 Gone	#2 Gone #3	Gone #4 Gone			٠
,			according as amende	to the county planed, (being the State State of Peer Review)	Survey and Remon	to P.A. 345 of	1990,
C De	scription of monume	ent for corner and accessories e	stablished to perpe	tuate locating the p	osition of the co	mer:	
4- 8		for Section 24, T23N,R15W.		•			,
	of the original	in dia. stamp accordinly and corner. Corner was set in er (3* pipe) S 50° E 39	is accepted as a nside a highway mo 9.86' to the face	careful and faith nument box. of pipe	2} o.d. steel p	ipe 30" long weent of the po	ith sition
	Yellow Pipe mark Power Pole N 7	S 32°W 81.80' (60d spike er (3" pipe) S 65°W 40. 2°W 33.80' (60d spike in l	.52' to the face o		4	LAND SURVEYOR No. 1 7 6 3 4	
Signed	1				17/8	HEO IN SURVEY	''.
Survey	or's Michigan Licen	se No1/424		FORM APPROVED	BY MICHIGAN STATE BOARD	іАС , ЗПОМВИДЦХ'СИВ ВОТО ІМ СВВІЧВЯ	N. 28, 1971 AY 14, 1976