LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in	Filing Require	ement of Act 74, Mich. P.A. 19		
1	Manistee		ì	REGISTER'S OFFICE	
	(County)	Located In:	Corner Code =##	MANISTEE COUNTY	
1.	Public Land Survey	T 23N _R 15W	A-04closing	#97-256 AT 11:13 A.m.	
		T R T R		REGISTER OF DEEDS	
2.	Property Controlling	S T R		- SELEDO	
	in Section	S T R			
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number	
	Property in Sec.	S T R		Trograter of Decad Statisf & File Hamber	
ı	Lakhia	December Miss			
		Recorded Plat		A B C D E F G H I J K L :	
J.	Frivate Claims			2 6 - 5 - 4 - 3 - 2 - 1 - 1	
				3	
	n			4 7 1 2 2	
ι, .	Bruce J. Jene	ema May in a field survey on May	01 97	5	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					
				7	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawland/or that the corner points mentioned in lines 3, 4 and 5				B 10 20 20 20 20	
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				·	
	ourt of Law; established, pressed below:	re-established, monumented, re-r	nonumented, recovered, found as	10 30 38 37 36 25	
	•			11	
M	on this certificate	corners, all in the same town ar	id range, may be recorded	12 3 32 33 34 35 30	
	Off this Certificati	G .		13	
A.	Description of origina	I monument and accessories and	d/or subsequent restoration:	(V	
				consist. Machine Mark Comm. New Yorks	
	A-04 closing W1 Sec. 7, T23N, R15W SULTVEY & This corner was not established by G.L.O.				
	THEO COLLECT			REMONUMENTATION	
				OCT 1 4 1997	
				COMMISSION	
В.	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
	L.C.R.C. #76-03 H.Bruning Set 5/8" iron from Road Commission witnesses and made the following witnesses: (1) 8" Apple NE 94.11' (2) 8" Apple ENE 74.18' (3) 6"J.Pine West 61.53"				
	(1) & (2) exist however no markings were on the Apple trees (3) Found stump Certificate of survey recorded Liber 2 of surveys page 635, Feb. 1996, by Ken Ross, also indicates acceptance of this corner by Anthony Slawinski.				
C	Corner A - D 4 c ratified by the Manistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument) Act, MCL 54.261 et. seq.). Date of Peer Review: MAY 6 1997 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
	On May 02,1997, I installed a Manistee County Monument, within a monument				
`	box in the exact location of the above 5/8" iron and this position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner and witnessed by:				
	(4) 30" Maple (5) 6" Cedar (6) Wooden ga	e S05°E 179.46' 6 S64°E 49.85' 60- ate post N90°W 33.	O-D spike N.side D spike N.side 95' 60-D N.side	SPE OF MICANOR BRUCE J. SP. BRU	
				\a\\\ surveyor\\\2\\	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Date June 2, 1997

Signed by Bruss J. Jenny Surveyor's Michigan License No. 25850