(m) ----

	LAND CORNER	R RECORDATION CERTIFICA	ې ATE	-CTION
	irement of Act 74, Mich. P.A	A. 1970		
For corners in Manistee (County)	Located In:	Corner Code #	TRIMANI	ER'S OFFICE TEE COUNTY 308 PT 11:51 P.M
1. Public Land Survey	T_24N R_14W T R T_24N R_13W T R	M-10 E¼ Sec 25 A-10	SEF <u>Plnny</u> BEGI8	O Repera TER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. Lot No, Rec. Private Claims	S T R S T R S T R R	W¼ Sec 30	Register o Number	f Deeds Stamp & File
under requirements of P.A. 74, I above were in conformance with survey instructions of the United by a decree of a Court of Law were in conformance with the J	Michigan P.A. of 1970, the corner regulations and rules therefore as d States Department of the Interio and /or that the corner points me	2_, 20_00 do hereby state that points mentioned in lines 1 and 2 s required in the current manual of or, Bureau of Land Management or entioned in lines 3, 4 and 5 above and Surveyors or by a Decree of a l, found as expressed below:	A B C D E 1 2 6 5 3 4 7 8	F G H 1 _{J K L}
NOTE: Not more than 2 co on this certificate.	rners, all in the same town and	d range, may be recorded	6 18 17	15 14 1
A. Description of original m East ½ Corner Section 25 (24-1: Set by John Brink in 1837. 1. Beech 12" in dia. S 28½° W 2. Beech 10" in dia. N 74° W	' 8 links (5.28')	or subsequent restoration:	19 20	28 27 26 29
Manistee County Surveyor's Red By E.W.M. in 1915. Book A, pa 3. Hemlock? in dia. N 45° E 7 4. Hemlock? in dia. N 45° W 5. Hemlock? in dia. S 45° E 7 6. Hemlock? in dia. S 45° W	ge 276 0.90 links (46.79') 70.90 links (46.79') 0.90 links (46.79')		13 32	33 34 35 3
Land Corner Record, by Kenneth Set 1" pipe with 4" brass cap by between section corners. 7. Cherry 8" in dia. N 64° E 3'8. Cherry 12" in dia. S 9° W 5	1 ½ links (20.79')	ec. 70-35)		Corner M – according to as amended, gt. seg.). Da
P.A. 74 form, by Larry M. Gersel Fd. DNR disc and pipe. 8. Cherry 16" in dia. S 10° W 9. Cherry 24" in dia. N 75° W 7. Cherry 12" in dia. N 60° E 2	34.80'	ec. 85-3)	·	to the county plan to the county plan sate Sate Sate Sate Sate Sate Sate of Peer Review:
East ¼ Corner Section 25 (24-14 On June 2, 2000, I Anthony M.	4) & West ¼ Corner Section 30 (2	from Abonmarche found a DNR disc	_	atified by the adopted purvey and Trained parts
C. Description of monument for East ¼ Corner Section 25 (24-14 On June 2, 2000, I accepted the original corner, and witnessed by 7. N 60° E 21.15′ 14″ Cherry	corner and accessories establishe 4) & West ¼ Corner Section 30 (2 5 DNR disc and Pipe as a careful ar 7: (fd 60d spike in S side of tree)	gone, #6 gone, #7 good, #8 good & d to perpetuate locating the position (4-13) and faithful re-establishment of the poor of th	n of the corner:	the Manistee County Peer pursuant to P.A. 345 of d Remonument Act, MCL
8. S 10° W 34.06′ 18″ Cherry 9. N 75° W 34.70′ 28″ Cherry 10. North 14.01′ Triple Maple	(fd 60d spike in S side of tree)	ANTHON'		r Group f 1990, 54.261

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: East ¼ Corner Section 25 (24-14) & West ¼ Corner Section 30 (24-13)
 On June 2, 2000, I accepted the DNR disc and Pipe as a careful and faithful re-establishment of the position of the original corner, and witnessed by:
- 7. N 60° E 21.15' 14" Cherry (fd 60d spike in S side of tree)
- 8. S 10° W 34.06′ 18" Cherry (fd 60d spike in W side of tree)
 9. N 75° W 34.70′ 28" Cherry (fd 60d spike in S side of tree)
- 10. North 14.01' Triple Maple (set 40d spike in E side of tree)

Corner is 12' North of centerline of Plagany Road, and is flush with the ground.



Surveyor's Michigan License No. 13597

7-26-00 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197
REVISED MAY 14,197
REVISED JAN., 198
REVISED OCT., 199