

## Commence of the Control of the Contr

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

-or	Corners in Manistee County (County)	Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY
i.	Public Land Survey	T <u>24N</u> R <u>13W</u> T R T R		10 1 1998
	Property Controlling in Section Miscellaneous	S T R S T R S T R		Register of Deeds Stamp & File Number
	Property in Section	ST R		negister of beeds stamp it the number
				A B C D E F G H I J K L M
⊃.	Private Claims			2 6 5 4 3 2
7	John C. Schulke	, in a field survey onMay	27th . 19 98	5 - 10 - 11 - 12
=mai Ma ≣5 a Dec ≡as ∈	nual of survey instruction agement or by a decree above were in conformant cree of a Court of Law; est expressed below:  OTE: Not more than 4 on this certificate  Description of origin M-10 East Quarter (May 9th 1838)  References: B	ons of the United States Depart of a Court of Law and/or that the ce with the rules of the Michigan stablished, re-established, monument corners, all in the same town as all monument and accessories Corner of Section 25, T24N, RI John Brink US Deputy Survey Seech 8" N46°W 17 links (Pages 112 & 113 W. A. Johns	and/or subsequent restoration: 3W or Set Wood Post. 1) Beech 7" S77°W 22 links on Deputy Wexford County Surveyor	d d 8 19 20 21 22 23 24 a g d d d d d d d d d d d d d d d d d d
В.	1987 Liber 4, 15" below roa Maple 24"  Description of corne M-10 East Quarter 0 Found 1/2" ca surface with w References 6.	d surface. Set 1/2" rerod #2841 N45°E 74.61 feet (6) Ner evidence found and/or methodor for section 25, T24N, R1 apped rerod 2" below road surfavith crockery and pieces of cast	hell Found 3/4" iron rod w/cast iron 17 over found iron. References: Maple 6" S44°E 51.40 feet (7 od applied in restoring or reestable 3W iron 5/4" iron bar 1.5' below iron around. References 1, 2, 3, 4 & part C. Measurement from M-9 to	7) Rerod 1/2" N85°W 7.10 feet (8) ishing corner: road & 5 are gone.
	M-9 Norti M-11 Sout	h 2663.32 feet	Corner M - 1 C	unty plan adopted pursuant to P.A. 345 of 1990, the State Suggest and Remonstrate Apt, MR1054.261
_	Description of man	ument for corner and accesso	ries established to perpetuate loca	ting the position of the corner:
C.	M-10 East Quarter Accepted the original corne Sugar Maple Sugar Maple 1/2" rebar Sugar Maple Center Line of	Corner of Section 25, T24N, R position of the 3/4" iron bar as and replaced with a standard I 30" N49°E 74.88 fee 14" S46°E 51.45 feet N80°22'E 7.04 feet	a careful and faithfully re-establishm Manistee County monument in a most t Set # 60 nail in SE side (6) Set # 60 nail in NE side (7) (Solar Bearing DNR Data) (8) Set # 60 nail in W. side (9)	ent of the position of the
	1	a Chal		FOLANDSU
Si	igned by	C & Kulke		ne 1st, 1998
S	urveyor's Michigan Lic	cense No. 30894	FORM APPRO	OVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975