## LAND CORNER RECORDATION CERTIFICATE

.....

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Manistee	Located In	Corner Code #			
(County)					
1. Public Land Survey	T 24N R 13W	E10			
Property Controlling in Section					
	S T R				
3. Miscellaneous	S T R				
Property in Section	s T R		Register of Deeds S	tamp & File Number	
4. Lot No:	Recorded Plat:		A B C D E F G	H i J K L M	
5. Private Claims:			2 6 5 4	3 2	
t, <u>Craig W. McVean</u> , in a field survey on <u>Sept. 11</u> , 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:					
NOTE: Not more than 2 corners, all in the same town and range, may					
be recorded on this certificate.			11	<del></del>	
			12 31 32 33	34-35-36-	
			13		
A. Description of origina	I monument and accessories and	d/or subsequent restoration	n:		
E10 GLO - Set Post, J. B			I.40' Chinese Elm		
<ul> <li>2) \$22°W 22 links (14.52') 6" Lynn</li> <li>Manistee Co. Surveyor's Record Book "A" page 261, W. H. Cook was working in Sec. 28, T24N, R13W; found no trace of old post. Established.</li> <li>3) \$28½"W 180½ links (119.13') 22" Beech</li> <li>Consumer's Power Co. fee strip survey by P. McPherson (#12023) in 1968, unrecorded survey. He found a railroad spike in line with fence to the West for the East ¼ corner of Sec. 29, T24N, R13W. No witnesses given.</li> <li>LCRC #74-06 G. F. DeLaMater (#13030) in 1974, was working in Sec. 29, T24N, R13W, fd. Railroad spike at surface in line with fence to the W. (no history or wit. given)</li> <li>Rec. Survey – L. 1 of surveys, p. 163, G. F. DeLaMater (#13030) in 1974, Sec. 29, T24N, R13W. Fd. Railroad spike at surface in line with fence to the west.</li> <li>LCRC #80-15 by J. L. Wilcox (14102) in 1980, found ½" rod and cap 2' west of Erwin Road centerline.</li> <li>4) \$30°E 89.60 24" Maple</li> <li>5) \$60°E 37.55' Pipeline marker (at ground)</li> <li>B. Description of corner evidence found and/or method applied in rest</li> </ul>		H. Cook rod w/ cap 2 4) \$30°E 89 5) \$60°E 37 6) \$N45°W 6' 7) \$70°W 36 1 - LCRC #03-0 of crew under l 2' west of ce pipeline that could find no h) Placed a sta of the above ike establishme 4) \$23°E 90 of tree 7) \$70°W 38 8) \$35°W 50	7) S70°W 35.88' Pipeline marker (top) 8) S35°W 50.41' 8" Double Ash (fd 60d spike on NW side of tree)		
E10 – ¼ Corner common to Sec. 28 & 29 – Excavated corner location per Co. Surveyor notes. Find pointed 5" x 9.5" x 11" granite stone lying on side just below original gravel road bed – Down 2.5'. Only large stone found during excavation. Stone probably graded over. Reset upright. Centerline of N-S gravel rd. is 5' W. Also find ancient fence wire running N, S, E & W from stone position. The Co. Sur. Rec. (CSR) indicated that Cook established this position by measuring 2 mile distance between 'E11' (fd. tile mon.) and 'E7' (Fd. Co. Mon.). We measure 10678' or 2669.7' per ½ mile between 'E10' and 'E7'. We measure South 2671.3' to fd. Tile from Stone. All the evidence indicated that this stone is the position established by Cook. Stone accepted as the best available evidence of the position of the original corner.					
- Reference Pt. – S56°39'W 8.2' of 'E10' found Manistee Co. Mon. in place of RR spike and ½" CIR per LCRC #03-077. Excavated around and under Co. Mon. searching for any other evidence to support this position but nothing else found. Fence called for to the West in gone. Can't believe RR spike was monument set by Cook. Reset Co. Mon. Manistee Co. monument not utilized as 'E10' in this survey.					
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					
N67°E 149.56' to 6) N40°E 52.80' 4) S25°E 90.97' 8) S32°W 57.59' 7) S61°W 43.96' 5) S45°E 34.30' S45°W 53.12' to	stamped 2 ½" Brass Cap on 5/8" o set N & T in S. side P. Pote. to fd. nail in SE side 40" Walnut to fd. nail in NE side 36" S. Maple to fd. nail in NW side of Tw. 13" to top Pt. of 2 ½" iron pipe pipeli to Chiseled '+' in face 2 ½" iron pfd. nail in 4" x 4" wood post. to Reference Pt. – Co. Mon.	e and 9" Walnut ne marker pipe Pipeline marker at bas	se	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No.	
Signed by: Surveyor's Michigan	ne W. Me 9  License No.: 39088	Date:	1/25/2007	39088 GA	
Su. reger o morngum				The state of the s	
		FORM APPROVED BY MICHIG	SAN STATE BOARD OF PROFESSI	IONAL SURVEYORS JAN. 28, 1971	