MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established while making a survey in this township. Unable to locate any previous corner in cut section of E-W road. Set corner in centerline of E-W road at Muenscher's record measurement from E 1/8 corner between 21-28, which also checks the record measurement west to W 1/8 between 21-28, and falls on line with 1/8 and section corner east and west. This method presumes to restore the corner as established in Muenscher's 1907 survey.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Lewell Statling DATE 11/15/61

REGISTERER CAND SURVEYOR