## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored while making a survey in this area. Set corner from probable remains of pine stump new bearing tree noted by E. W. Muenscher in a 1907 survey. Corner falls in a Hemlock stump bottom, which was concluded to be the original corner tree. Falls in E-W fence line and appears to be the best available evidence of proper location for corner.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Kunth JOtling DATE 11/15/61
REGISTERED KAND SURVEYOR