

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 24 NR 13 W
T 24 NR 14 W

Manistee COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 18 and 13

DESCRIPTION OF CORNER MONUMENT Left 1" pipe in place.

WITNESSES TO CORNER

5" J. Pine - N66W - 119 links

8" R. Pine - S26W - 135 1/2 links

Fence corner - East - 50 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in T24N, R14W. Found 1" pipe in place in line with fence east. Appears to have been accepted as corner by occupation and checks good with section corner north. One of few corners available for control of retracement in this township.

Corner was witnessed October 6, 1960.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling DATE 10/10/60
REGISTERED LAND SURVEYOR