## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
	I. PUBLIC LAND SURVEY	T. 24 N., R. 14 W	A-7; B-7; D-6; E-6	
	2. PROPERTY CONTROLL- ING IN SECTION——	,T N E		
	3. MISCELLANEOUS PROPERTY IN SECTION	N. T S., R W		
	1. LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
	Carl F. Roser	, do hereby	certify that under requirements	of P.A. 74, Michigan P.A. of 1970,
	re-established, monumented, re-rand rules therefore as required in Bureau of Land Management or	nonumented, recovered or the current manual of sur by a decree of a court of la	restored as expressed below and recy instructions of the United w. Furthermore, that the corner is 19 found, recovered, respectively.	0 , 19 78 , established, d in conformance with regulations States Department of the Interior, er points mentioned in lines 3, 4 stored, established or re-established tration for Land Surveyors or, by a
	YA KARAKARA KARAKARAKARAKARAKARAKARAKARAK	o kankaran kanakaran b	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
	C. continued		E-6 , Mon. & Set Ced.Post w	/Loc. Tag.
		6" Scoto	ch Pine NO5°W 3	1.64
		10" R.Pir P.Pol		2.38 .45
•		Fd. Conc.		.97 !+
		<b>0011</b> 511.	(2.7 2.2.2.)	_
A-7 B-7 D-6 E-6	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Fd. 1" pipe as recovered by W.D. Manchester in 1926; previous Dept. Corner of record, 1966 Fd. and accepted 1" Ir. Rod, in line with old N-S fence on to North. The occupancy at this corner would seem to fit old survey of NE 1/4 of Sec. 19 by J.H. Millard, March 1897. Fd. Iron also fits Road Comm. data which indicates they found an iron in 19 Recovered position for center of Sec. 17 from two W.Pine stump remains of J.H. Millard Wits., 1881 to 1901. Old Cor. fn. post, fn. remains N&E, is 19'+ South & 9'+ E. Fd. and accepted Conc. Mon. per survey of NW 1/4 of Sec. 16, Gourdie, Miller, Batzer, 19 Corner fn. post (fn. N&W) is 3'+ N. & 4'+ W.			
	C. Description of monument fo	corner and accessories est	ablished to perpetuate locating the B-7	he position of the corner: D-6
Fd.	1" pipe & Ced.Post w/Lo	c.Tag. Fd. 1" so	lid Iron Rod 10" below ce, raised w/5/8"X10"	Set 5/8"X40" re-rod &
	Dead Elm S24°E 32 Elm Stump S57°W 50	.9 re-rod $w/v$	olastic cap.	5" W.Pine N40°W 60.6
10" C+=	Cherry N60°W 118	.91 18" Maple	S08°E 56.10 N16°E 56.51	5" W.Pine S80°W 92.8 E-W random line to east
ULI.	Due N 105	'+ 17" Maple	N72°E 91.66	5" W.Pine S80°W 92.8 E-W random line to east Due N. 11.8'
		Ctr. E-W	B.Top Rd.  Due S. 0.5'+	and the second
	A 4 5			WHAT OF MICKING
	SIGNED BY Carl T	Roser 2-2	26-79 DATE	CARL'
	SIGNED BY Carl 7, Roser 2-26-79 DATE  SURVEYOR'S MICHIGAN REGISTRATION NO. 12028  CARL F. ROSER LAND SURVEYOR  NO. 10000			
	BOD CRATE AND IMITED S	TATES ACENCIES.		12028 SURLING
	SIGNED BY	CHIEF OF CURVEY STATE	DATE	TARED LAND SUMME
	SIGNED BYAPPROVED AND SIGNED BY	CHIEF OF BURYET PARTY	DATE_	
		MICHIGAN REGISTERE	A PULL AND LAN	(SEAL)
	SURVEYOR'S MICHIGAN RE	CISTRATION NO		PRINGDALE TOWNSHIP

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1975