LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N. S., R. 14 E. W.	K-8, K-7, I-8, I-7
2. PROPERTY CONTROLLING IN SECTION 23	,T. 24 N. S., R. 14 E. W.	7, 2
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on APRIL 20, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (CONT.)

K-7
FD DNR MON (W/BRASS CAP); ADDED CED POST.
8" BALSAM N60°E 93.7
6" MAPLE N15°E 77.2
9" R PINE N35°E 99.0

I-8
SET DNR MON & CED. POST.
6" W PINE DUE S 22.2
9" W PINE S60°E 40.8
8" W PINE N65°E 20.8
N-S RANDOM WEST 1'

I-7
FD DNR MON W/BRASS CAP; ADDED CED POST.
9" CEDAR S50°W 56.6
6" MAPLE S80°E 30.7
10" MAPLE N10°E 38.3

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-8 RECOVERED DEPT MONUMENT; 1960 S.P.
7 RE-ESTAB N 1/8 COR ON E. LINE OF SEC 23 PER STD B.L.M. INSTRUCTIONS.
2 ESTAB E 1/8 COR ON N LINE OF SEC 23 PER STD B.L.M. INSTRUCTIONS. CUT IN TRUE LINE E & W.
K-7 RECOVERED DEPT MON; 1960 FROM G.L.O. SURVEY EVIDENCE AND PRO-PORTIONATE MEASUREMENT. CUT IN TRUE LINE N-S-W.
I-8 RE-ESTAB W 1/4 COR OF SEC 23 MID-WAY & ON LINE BETW. THE NW & SW COR'S OF S-23.
I-7 RECOVERED DEPT MON; 1960 FROM G.L.O. SURVEY EVIDENCE AND PRO-PORTIONATE MEASUREMENT.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-8
FD DNR MON(W/BRASS CAP) & ADDED CED POST.
*6" CED N30°E 16.4
*7" CED S10°E 13.6
6" CED S25°W 26.9
N-S RANDOM WEST 4'±

7
SET 3/4" X 84" PIPE W/RLS CAP & CED. POST W/LOC TAG.
6" MAPLE S30°E 11.7
*5" CEDAR DUE E 19.7
*7" W PINE(TW) S50°W 23.9
5" MAPLE N30°E 18.4
N-S RANDOM WEST 2'±

2
SET 3/4 X 84" PIPE W/RLS CAP & CED POST W/LOC TAG.
4" MAPLE N10°W 8.0
11" MAPLE S75°E 59.6
8" CHERRY N50°E 45.5

* OLD K.J.O. WITS

* OLD K.J.O. WITS.

SIGNED BY Carl F. Roser 05-02-83 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN
CARL F. ROSER
(SEAL) LAND SURVEYOR No. 12028
REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

SPRINGDALE TWP.
MANISTEE CO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET