LAND CORNER RECORDATION CERTIFICATE

For	corners in	Filing Require	ment of Act 74, Mich. P.A. 19	970
-	anistee	Located In:	Corner Code ≠#	REGISTER'S OFFICE
1.	Public Land Survey	т <u>24N</u> в <u>14W</u>	F-5 (S ¹ ₂ 9)	MANISTEE COUNTY # 95-394 AT 1:43 p.m. OCT 0 9 1995
2.	Property Controlling	T R T R S T R		REGISTER OF DEEDS
2	in Section Miscellaneous	S T R S T R	- Andrew Martin Comp. Topics of Martin Comp.	
J.	Property in Sec.	S T R		Register of Deeds Stamp & File Number
4.	Lot No.	Recorded Plat		A B C D E F G H I J K L
5.	Private Claims			2 6 5 4 3 2 1
		,		3
~		A	14 05	4 7 - 12
do t in li curi Mar abo Cou exp	nereby certify that under re ines 1 and 2 above were rent manual of survey inst nagement or by a decree of ove were in conformance w art of Law; established, pressed below:	in a field survey on <u>Septem</u> equirements of P.A. 74, Michigan P.A. on conformance with regulations and ructions of the United States Depart fa Court of Law and/or that the corner with the rules of the Michigan Board of re-established, monumented, re-marked	of 1970, the corner points mentioned if rules therefore as required in the ment of the Interior, Bureau of Land points mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a conumented, recovered, found as	7 8192021222324 910302928272625
NO	TE: Not more than 4 on this certificate	corners, all in the same town an	a range, may pe recorded	. 11
	On this certificate	••		13
	Book A, page 26	y: Hemlock 14" S10°E 13 7, 1915 J.H. Mallard ce line, Midway and on	set cast sleigh shoe	V17°W 21 links 25 links West of nd SE corners of Section 9
₿.	LCRC #73-4 Car Witnessed by: [[3] Centerline Found 3/8" dia.	evidence found and/or method a 1 F. Roser Fnd 3/8 spik 1] 12" Twin Maple S63° E-W B. Top Road Due Sou pipe with 3/8 spike ir ing this site in search	te Found to fit recorder 103.9' [2] 5" R. Pinth 3.8' [4] concrete not center; Found 3/8' di	ed plat of Old Grade Crossing ine S30°E 54.5' nonument North 33.0' La pipe 0.72' East
`.	a. a	omer $F - 25$ ratific coording to the county plan adopt amended, (being the Gate Surve), Legs.). Date of Peer Review: 4	oted pursuarit to P.A. 345 of 19 y end Remonument Act, MCL 54.	90, [2] (Likip) [5]
C.	Description of monum	ent for corner and accessories e		g the position of the corner.
	and installed a monument box and [1] 12" Twin so:	5, accepted 3/8" iron pd faithful re-establish 2"x30" stainless steeld witnessed by: ft Maple S63°E 104.2 S S30°E 54.65 N80°E 161.00 S75°W 106.88	pipe with a brass ID let 60-D spike N. side	cap enclosed within a
Sig	gned by Baz	uce I. Jinon	Date Sept	ember 29, 1995
Su	rveyor's Michigan Licer	nse No 25850		A APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28.