LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

as low back at a back the

For corners in			ı
Manistee	Located in:	Corner Code #	
(County)			
1. Public Land Survey	T 24N R 14W	K-13 V	

REGISTER'S OFFICE MANISTEE COUNTY 00-300 at 11:35p.n.
SEP U 3 2000

Plany a. Repea REGISTER OF DEEDS

Register of Deeds Stamp & File Number

SE Sec Corner Sec 35 23N R 14W 2. Property Controlling **NE Sec Cor** in Section Sec 2 3. Miscellaneous Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims

I, Anthony M. Slawinski , in a field survey on <u>June 23</u>, 20 <u>00</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration: Southeast Section Corner Section 35 (24-14) & Northeast Section Corner Section 2 (23-14) Set by John Brink in 1837.
- 1. Black Ash 11" in dia. N 36° E 18 links (11.88')
- Black Ash 13" in dia. N 80½° W 23 links (15.18')

DNR Map of part of T24N, R14W (includes Section35) Found Boat Spike, no witnesses.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Southeast Section Corner Section 35 (24-14) & Northeast Section Corner Section 2 (23-14) On June 23, 2000, I, Anthony Slawinski, along with a field crew, found a Cabin spike in the centerline of 13 Mile Road, 33' North of DNR location post. We found no other evidence to dispute this location for the corner.

Condition of witnesses: #1 gone, #2 gone

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Southeast Section Corner Section 35 (24-14) & Northeast Section Corner Section 2 (23-14) On June 23, 2000 I set a Manistee County Monument in a monument box in the exact location as the above mentioned Cabin spike as a careful and faithful re-establishment of the position of the original corner, and witnessed by:
- 3. S 40° E 67.50' 24" White Pine (fd. 40d flush with bark)
- 4. S 07° E 81.47' 30" White Pine (set 40d west side of tree)
- 5. N 09° W 40.18′ 6″ Maple Clump (set 40d on east side of tree)
- 6. S 38° W 44.94' 6" White Pine (set 40d on west side of tree)

Found DNR post 33' south of corner. Corner is in centerline of 13 mile road.



Corner K - 13 ratified by the Manistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54,261

et. seg.). Date of Peer Review: 7-31-00

Authory m. Slawinsli

SLAWMSKI Surveyor NO. 13597

anthony m. Slawinski

7-26-00

Surveyor's Michigan License No. 13597