LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 24 N., R. 15 W.	J-8; J-9
2. PROPERTY CONTROLLING IN SECTION 23	,T. 24 N., R. 15 W.	10; 12
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on May 23, 19 75, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

12

Set 1¼"x36" pipe & cedar post w/loc. tag

9" Cherry	N30°E	107.3
6" R. Pine	S20°E	21.3
6" Maple	N58°W	104.7

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-8 Recovered J.H. Millard stake bottom & stone, from one remaining witness, for center of Sec. 23, per J.H.M. survey dated 1907.

J-9 Reestablished corner on split-up of old R.O.W. maple trees to west and in line w/fence remains (buried) to N & S & old fence posts on hillside to S. Corner fits Millard split-up of Sec. 23, in 1907; see large red co. surveyors book, p. 289, at Reg. of Deeds.

10 Established corner equidistant & on line between ¼ corner N & sec. corner S.

12 Established corner equidistant & on line between center of Sec. 23 & S¼ corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-8

Found rock & stake bottom, set 1¼" pipe & ced. post w/loc.tag

9" Maple	N58°W	18.4
13" Cherry	N02°W	55.1
7" Maple	N45°E	61.3

J-9

Set 1¼"x36" pipe (buried)

36" Maple	S65°W	69.50
39" Maple	N38°W	39.34
8" R. Pine	N33°E	86.23

Set cedar post w/loc. tag Due N 33'

10

Set 1"x36" pipe & post w/loc.tag

9" Maple	N15°W	11.8
5" Maple	S88°E	19.2
7" Maple	S22°W	71.0
14" Ash	S66°W	5.6

SIGNED BY Carl F. Roser 9-4-75 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

PLEASANTON TOWNSHIP
MANISTEE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN 28 1971
REVISED MAY 14 1975

MAY USE SKETCH ON BACK AS NECESSARY