- Chicky

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

 $\int_{\mathbb{R}^{n-1}(\mathbb{R}^{n})}$

REGISTER'S OFFICE

Manistee (County)	Located in:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY OO - aga ないころうかの
1. Public Land Survey	T <u>24N</u> R <u>16W</u> T R	L-13 S¼ Sec 36	SEP U 3 2000 Ferry a. Fepera BEGISTER OF DEEDS
2. Property Controlling S	TR TR TR TR TR I Plat		Register of Deeds Stamp & File Number
I, Anthony M. Slawinski, in a under requirements of P.A. 74, Michiga above were in conformance with regula survey instructions of the United State by a decree of a Court of Law and /owere in conformance with the rules of Court of Law; established, re-established. NOTE: Not more than 2 corners, on this certificate.	an P.A. of 1970, the corner ations and rules therefore a is Department of the Interi- ir that the corner points ma- the Michigan Board of La ed, monumented, recovered	r points mentioned in lines 1 and 2 is required in the current manual of or, Bureau of Land Management or entioned in lines 3, 4 and 5 above and Surveyors or by a Decree of a d, found as expressed below:	A B C D E F G H I J K L M 1
A. Description of original monume South ¼ Corner Section 36 (24-16) Set by John Brink in 1838 1. Beech 8" in dia. N 29½° E 35 links 2. Beech 6" in dia. N 37½° W 31 links	s (23,10′)	or subsequent restoration:	8 19 20 21 22 23 24 9 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
Certificate of Survey, by Anthony M. S Fd. PK Nail, 3. Jack Pine 10" in dia. N 30° W 68.6 4. Jack Pine 12" in dia. N 15° W 77.5 5. Jack Pine 10" in dia. N 5° E 56.56	51′ 71′		13
Certificate of Survey, by Bruce J. Jene Fd. #60d Nail 5. Red Pine 8" in dia. N 8° E 56.50' 6. Phone Box S 75° W 104.00' 7. White Pine 12" in dia. S 50° E 81.4			
Certificate of Survey, by Daniel B. Zwa Fd. PK nail. 3. Pine 10" in dia. N 30° W 68.61' 4. Pine 12" in dia. N 15° W 77.71' 5. Pine 10" in dia. N 5° E 56.56' C/L E-W Road	r RLS #28435, in 1999.		
B South ¼ Corner Section 36 (24-16).	Description of corner	evidence found and/or method	applied in restoring or reestablishing corner:
On June 16, 2000, I Anthony M. Slawi 13 Mile Rd. We found no other eviden	=		in the centerline of
Condition of witnesses: #1 gone, #2 g	one, #3 good, #4 good, #	5 gone, #6 gone & #7 gone	
C. Description of monument for co South ¼ Corner Section 36 (24-16 On June 16, 2000, I installed a Ma a careful and faithful re-establishm	3) anistee County Monume	nt, in a monument box in the ex	xact location of the above mentioned PK nail as
3. N 30° W 67.55′ 12″ Jack Pin 4. N 12° E 77.33′ 14″ Jack Pine 8. S 29° E 60.51′ 10″ Pine (fd. 9. N 05° W 60.51′ 10″ Pine (set	e (fd. nail & washer in E 60d spike in E. side of t t 60d spike in E. side of	side of the side of the second state of the second	ratified by the Manistee County Feer Group plan adopted pursuant to P.A. 345 of 1930, State Survey and Remonument Act, MCL 54.261 eview: 7-31-00 Anthoy m. Slawnsh
Signed by <u>Authory 'M</u> Surveyor's Michigan License No. <u>1</u>	Lawins	ANTHONY SLAWINSKI	Date 7-26-00 Date 17-26-00 EN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED DCT., 1995