## SURVEY & REMONUMENTATION

JAN 2 3 2001

	LAND CORNER	RECORDATION CERTIF	CATE						
SECTION Filing Requirement of Act 74,		ment of Act 74, Mich. P.A						4	
For corners In:	Located In:	Corner Code #	AT.	4:1	1	O'CLOC	K	<u> </u>	
Mason County		Ť			0	0.0	0000	7	
1. Public Land Survey	T_17N R_17W T R TR	<u>G6</u>		MA	Ou: RGARET	KOLAS	<b>X) EL L</b> !!	) IT	
2. Branchi Cantalita ' C	TR				MAS( REGIST	ON COL ER OF L	ETY Ett 2		
2. Property Controlling S S S S S S S S S S S S S S S S S S S	T R T R T R T R T R T R T R R T R R T R T R R T R		Regis		Deeds S				er
4. Lot No. Recorded	Plat			, A B	C D	E F (	<b>∌</b> H ↓	ı j K	L
5. Private Claims				2 6	5	4	3	2	,
I, Kenneth L. Ross in a field surve	y on September 18, 2000, I	Do hereby certify that under		3 4 7	8	,	10	11	1;
requirements of P.A.74, Michigan above were in conformance with re	P.A. of 1970, the corner poi egulations and rules therefo	nts mentioned in lines 1 and re as required in the current re	nanual	5	<del> </del>				-
of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by				6   18 7	17	16 >	( 15	14	1.
a Decree of a Court of Law; estable recovered, found as expressed be	ished, re-established, mon	igan Board of Land Surveyor umented, re-monumented,	- '	8 19	20	21	22	23	2
% comer common to sections c		nd 16 of T17N. R17W		30	29	28	27	26	2
A. Description of original monument and accessories and/or subsequent restoration;			n:	2 31	32	33	34	35	34
GLO Hodgson 1838 Set qr. sec. post I survey Mason County Rd.	John A. Mitchell March 1880 B1, P86 & 87	Stephens 1953 Riverton Schoo	1	ı3 L	_1	I	<u> </u>	<u> </u>	L
Elm 24" N47W 15 lks. (9.90') #1 Identified standing witnesses Did not show this cor. Elm 18" S23E 11 lks. (7.26') #2 Showed S 1/16 cor. location			""	"2" x 4" iron, stone, fences approx on line." No witnesses given.					
Ross RLS 17634 LCRC July 1973 L1, P196 Set 1/2" rebar at double 1/8 cor. Dist as est. by K. Stephens 1955 Riverton School survey. Cen. rd. on old E-W fen. PP SE 204.48" #3 PP NE 183.48" #4 B. Description of corner evidence	Towns June 1904 B2 P114 & 115 "located this ¼ post by iron" no witnesses taken se found and/or method a	Ross 17634, 1973 Same as LCRC L1 P196 pplied in restoring or reest							
I found a 1/2" x 18" iron rod in a monumen	t box in the centerline of a North	-South Road. Evidence of old fer	nce row Eas	st and W	est.				
Condition of the accessories is as follows	3: 1 and 2 are gone 3 and 4 are	in good condition but no nails wen	e found.						
I found nothing to dispute the location of	this comer.		-						
C. Description of monument for	corner and accessories	established to perpetuate lo	ocating ti	he posi	tion of	the co	ner:		
I replaced the ½" x 18" iron rod with a 5/6 and faithful reestablishment of the position	" x 24" iron rod with a 2 1⁄2" alum on of the original corner.	ninum cap stamped "Mason Count	y Monumer	nt PLS 17	'634". I s	ccepted	this as	a carefu	IJ
PP S11E 204.34' (set mag. nail on W. si PP N20E 183.34' (set mag. nail on W. si Distance South to G-7 = 2541.20' #5 Distance North to G-5 = 2568.97' #8	de) #3 de) #4			Annummer .	. # 	OF M JETH L. LAND SURVEY No.		The state of the s	
	100 .			113		7 6	3 4 SURY	China	
Signed by (	Fran	Date <u>10-09</u>	-200	OS	•		. • -		
Surveyor's Michigan License No. 17634		FC	ORM APPROVE	BY MUCHIGA	NATATE BO	ARD OF LA	NO SURVEY	rors, Jan	28,
Approved by Peer Review Group on	0-05-700E	R	971 EVISED MAY 14 EVISED JAN., 11						