

DEC 2 9 1998

LAND CORNER RECORDATION CERTIFICATE

SECTION	Filing Requ	iirement of Act 74, Mich	. P.A. 1970	Ţ.,	*FLED®		. 3	1
For corners in				1	ULLI (LA)		10	
MASON	Located In:	Corner Code #	AT	10 "	OCTOCK	70	M	
(County)	_	3011101 3333 11				. 12		ļ
			11	or.	b t 1 oo	1 '	· .	
1. Public Land Survey	T tou D tou			SE	6. 1999	8		1
1. Fublic Land Survey	T 19N R 16W T R	G-6	11			ı		
	T R		1 1	MARY C	OLDEN KO	AOV		1
	† R			141741 G	SON COUNT	LASKI		1
2. Property Controlling S				DF(34)	TER OF DE	T TDO		Į
in Section S				1,170,0	TER OF DE	:US		j
3. Miscellaneous S			Regis	ster of D	eeds Stamp	2 File	Numb	Ar
Property in Sec. S	T R							••
4. Lot No, Rec	orded Plat			, A B (DEF	ені	1 K	1 M
5. Private Claims				1		1	, , ,	L
				2 6	5 4	3	2	1
				3				
L Kenneth L. Ross	, in a field surv	eyon August 25 19 9	8 .	4 7	8 9	10	11	12
do hereby certify that under requ	, in a field surv uirements of P.A. 74, Michigan P.	of 1970, the corner points ment	ioned	5	" "	"	''	14
in lines 1 and 2 above were in	6 18			_				
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5					17 16	9 15	14	13
above were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decre	eofa	7		 		
Court of Law; established, in	re-established, monumented, re	-monumented, recovered, foun-	d as	8 19	20 21	22	23	~ 24
expressed below:				۰				
NOTE: Not man than 4 a	amona all in the cases town			0 30	29 28	27	26	25
on this certificate.	orners, all in the same tow	n and range, may be recor	G8G		27 20		20	20
on this continuate.	•			l i	00 00		0.5	0.1
A. Description of original	monument and accessories a	ind/or subsequent restoration		2 31	32 33	34	35	36
G-6 1/4 Corner for Se	ctions 15 and 16, T18N-R	16w.	1	13				
1838, Slyvester S	White are	1076						
Set Wood Po			Ross, RLS #: Pipe in mor		юж			
	N 22 E 25 lks. (16.50')		. no. E-88,			5s., 96	294s.)
#2 Beech 10"	8 61 W 14 1ks. (9.24')							
1972, N. C. Jones	. RLS #02934							
	Pin inside 1 1/4" pipe,	inside						
monument bo								
#3 Guy Pola N #4 Ash 24" 8								
	S 54 W 51.28'							
(liber 1 pa								
B. Description of corner every G-6 1/4 Corner for S	vidence found and/or method	applied in restoring or reest	ablishing corn	er:				
								
On A	ugust 25, 1998, I found	a 3/4" Iron Pipe inside	an 1 1/4" II	on Pipe	, inside a	n exist	ing	
monument box, a	t the center-line of U.	S. 10. I found no evi	dence to dis	pute th	is location	n.	,	
Condition of re	cord witnesses are as fo	llows; #1 Gone #2	Gone #3	gone	#4 Found	in goo	d cone	1.
• •				-		-		
#5 Found in go	od condition							
•								
C. Description of monume	ent for corner and accessories eations 15 and 16, T18N-	s established to perpetuate lo	ocating the po	sition of t	the corner:			
274 6521152 252 5	ections 13 and 10, 116N-	NAOW.					_	
I a	ccepted 3/4" Iron pipe is	nside a 1 1/4" Iron pipe	, inside a m	onument	box, as a	subs ça	ntial	
marker for the co	orner. This Corner is ac	cepted as a careful and	raithful re-	establi.	shment of	the pos	resou.	ο£
,y	· •				A Comment	ETH: #	nace *	: ⁻
ext. "BT" #4 Ash 30"		.K. nail in SW side of t					ta92 🧳	
ext. "BT" #5 Power Pole new "BT" #6 Power Pole	S 54 W 51.10' (for N 43 E 51.81' (se	und 16p w/ shiner in SE t P.K. nail in NW side o	side of pole f pole)))		- ξ υ(40) -		
			77,61'		<u> </u>	• •	,	. :
						- Na 7 - 2 - 2	1 ."	1.5
						7 3		
Cincadhu —	Sel 1	.	. //	, ,,-	و المارة المارة من سير	П~д		*
Signed by	1 1 for	Date	apr E		<u> ブス 🌝</u>	<u> </u>	31,**	
Surveyor's Michigan License	No. 17634		FORM APPROVE	D BY MICHIGAN	STATE BOARD OF	LAND SURVE	YORS, JAN	. 28, 1971
• • • • • • • • • • • • • • • • • • • •						PCE	NEVISED I	14, 1875
					ADAPTED FOR V	VORD PROCE	BSING MAF	ICH 1993