

MAY 6 7 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For a serious In	Filing Requ	uirement of Act 74, Mi	ch, P.A. 1970	
For corners in			FILED	
Mason L (County)	_ocatéd In: C	orner Code #	AT 9:29 0'CLOCK.	_a_N
1. Public Land Survey	T18N R 17W T R	J-07		S
w.	TR TR		0CT - 3 igo	6
2. Property Controlling S In Section S	T_R		MARY GOLDEN KO MASON COUN	
3. Miscellaneous	; TR		REGISTER OF DE	EDS
Property in Sec.	· /		Register of Deeds	Stamp & File Number
4. Lot No, Recorded	l Plat			
5. Private Claims			A B C D E F	G H I J K L M
	·		2 - 6 5 4 -	1-3-1-2-1-1-1
. Cammu C Bannatt .	- Fald Sont	40 Of de benefit et	3	10 11 13
t, Sammy S. Barnett , in requirements of P.A. 74, Michigan P.	A. of 1970, the corner points	mentioned in lines 1 and 2 a	pove were in _	
conformance with regulations and rules	s therefore as required in the o or Bureau of Land Manageme	current manual of survey instr ent or by a decree of a Court o	ctions of the Law and /or 6 19 17 16	15-1-14-1-13-
that the corner points mentioned in lin Board of Land Surveyors or by a C	nes 3 4 and 5 above were in c	conformance with the rules of	he Michigan _	
recovered, found as expressed below:	secree of a Court of Law, e	stablished, re-established, r	8 19 20 21	222324
NOTE: Not more than 2 corners,	all in the same town and ra	nne may be recorded	9	
on this certificate.			10 - 30 - 29 - 28	27-1-26-1-25-
		•	11	
			12 -31 - 3233	34 35 36
A. Description of original monum J-07 1/4 Corner common to Sc. 1838 Syl. Sibley G.L.O. Set Post #1 Lynn 10" N8E 15 1ks #2 Beech 8" S60E 9 1ks. 1911 R.O. Towns Co. Sur Stone (no witnesses) Un-dated M.C.R.C Stone with cross B. Description of corner evidence	ections 14 & 23, T18N . #3 Maple : #4 Elm 4" (9.9') #5 NE cor . (5.94') 1966 K.B. rveyor Found 3/4' #6 Trans. #7 Tel Po	, RI7W (Amber) 36" N70E 135' S44½E 53' porch S35W 91.4' Stephens " Pipe Pole S.E. 78.7' le SW 44.2' 36" N.E. 135.0' (#3)	1974 J. Borsfay M.C.R.C. Found 1" Pipe .5' below surfact #9 Trans. pole S.E. 79.3' (#6 #10 Tel Pole S.W. 44.58' (#7) #11. Tel. Guy Pole N.W. 111.35 1974 Barry G. Krebs B.L.M. Found 3/4" Pipe (no new witnes	;) ;•
J-07 1/4 Corner common to Se	ections 14 & 23, 718N	, R17W (Amber)	,	
on Sept 6, I found a 1" pipe condition of the recorded w		ment box. I found no	evidence to dispute this locat	ion. The
# 1 Gone	, , , , , , , , , , , , , , , , , , ,	# 9 SAme as # 6	# 17 Same as # 6 % 9	
# 2 Gone	till sotte to en elde	# 10 Gone	# 18 Same as # 7 & 10	in Cu eide
#. 3Maple 48" N75E 135-96' at # 4 Gone	aged spike in 3c side	# 12 Gone	# 19 PP. TP 54.03 spike	111 JW 3106
# 5 Did not check		# 13 Gone		
# 6 Gone # 7 Gone		# 14 Gone # 15Gone		
# 9 Camp ac # 3		# 16 Same as # 3 &	8	
C. Description of monument for a J-07 1/4 Corner common to Se	corner and accessories es actions 14 & 23 T18N	tablished to perpetuate lo	eating the position of the corner:	
I set a Standard Mason Coun	nty Monument, in the e as a careful and fait spike in SE side W 45.03' spike in SW ' Spike in SW side	exact location of the chful reestablishment side	I" pipe inside of the existing of the position of the origina	SAMMY S. BARNETT
0	0 -		E.	SURVEYOR O
Signed by Sammy &	Barnett		Date 9-25-96	16923
Surveyor's Michigan License No.	16923			OFESSIONA
:	Pece Group Reviewed		â.	

Mason County Surveyor

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983
REVISED OCT., 1995

57

J-07 1/4 Corner common to Sections 14 & 23, T18N, R17W (Amber)

1978 K. Ross Found 1" Pipe #12 Tel Pole S40W 44.51' (# 7 & 10) #13 Tel Pole N70W 111.29' (# 11) #14 Rd. Name Sign S50W 52.661 #15 Power Pole \$30E 77.04'

1984 L. Slater M.D.O.T. Found 5/8" x 13" Bolt in 1" Pipe along e. side of large stone. #16 42" Maple N78E 135.88' (# 3 & 8) #17 PP w/trans S36E 79.31' (# 6 & 9) #18 Tel Pole S50W 44.98' (# 7 & 10) #19 PP, TP N30W 44.50'

1990 K. Ross Found 1" square iron No new witnesses