SURVEY & REMONUMENTATION

JAN 2 3 2001

SECTION	LAND CORNE	R RECORDATION CERT	TIFICATE	=	 .						
	Filing Requirement of Act 74, Mich. P.A. 19			o FILED AT <u>9:44</u> 0'CLOCK A. N							
For corners In: Loca	ted In:	Corner Code #	A.	T	<u>9:47</u>	0	'CLOC	(_ <i>H</i>	2	N	
Mason County						AUG	1 : 2	000			
1. Public Land Survey T 18N T T	N R 18W K-13 R R R				MARGARET KOLASKI ELLIOTT MASON COUNTY REGISTER OF DEEDS						
Property Controlling S T T In Section S T	R R R		Reg	giste				EEDS & File	Numb	ər	
4. Lot No, Recorded Plat 5. Private Claims				, /	А В	C D	E F (3 H E	J K	L	
3. I mate claims				2	6	5	4	3	2	1	
I, Kenneth L. Ross in a field survey on Jun of P.A.74, Michigan P.A. of 1970,the corne	e 21, 2000, Do he	reby certify that under requed in lines 1 and 2 above we	irements ere in	4	7	8	9	10	וו	1	
conformance with regulations and rules the instructions of the United States Department	erefore as required ent of the Interior, i	d in the current manual of s Bureau of Land Manageme	urvey nt or by a	6	18	17	16	15	14	1:	
decree of a Court of Law and/or that the coin conformance with the rules of the Michigof Law; established, re-established, monur	an Board of Land	Surveyors or by a Decree of	f a Court	8 9	19	20	21	22	23	2.	
expressed below: Section corner common to sections 35	and 36 of T18N. I	R18W.		10 11	30	29	28	27	26	24	
A. Description of original monument an			ion:	12	31	32	33	34	35	34	
GLO Mullett & Brookfield 1838 Set Post		an. 1977 LCRC L 1 P329		13 l Hav	s 1988	L L378 P2	91)	
8° E. pine N40W 31 Lks. (20.46') #1 9° Beech N18E 15 Lks. (9.90') #2 Stephens RLS 7318, unrecorded 1967 Stone & iron stake Rd. sign S51E 50.21' #3 PP #47 N50E 69.15' #4 Tel. J box N30W 56.06' #5	90') #2 PP N55E 69.09' #6 18" pine N30W 61.85' #8 corded 1967 PP S40E 95.01' #9 n S51E 50.21' #3 Guy pole N45W 46.07' #10			No identification or witnesses Fluharty L342 P18 1986 Fd. 1" bar in mon. box 12" spruce N26W 61.84' #8 PP S28E 185.68' #11 PP N72W 157.05' #15							
LCRC Ross PLS 17634 L1 P32 1972 Fd. 5/8" iron	Placed boat spike in monument box PP S36E 185.35' #11 Guy pole N45W 62.30' #12			Ross (unrecorded 1992 & 1997) iron in mon. box. No. wit.							
PP N48W 68.98' #6 Street sign S49E 50.30' #7 Cedar clump N2W 61.80' #8		of S. conc. rail S85E 303.14 #1 of N. conc. rail N85E 313.97 #14				ţ					
B. Description of comer evidence found	i and/or method a	applied in restoring or ree	stablishi	ng c	orner:						
I found a boat spike in a monument box Cen. Rd. to T17N, R18W is East 26.53'	o S. is 5' East, Cen. o	of Rd. to N. is 10' East, Cen. of E	-W Rd. is 1	1.4° N	lorth. C	omer fo	r section	1 and 2	? of		
The condition of the accessories are as follows: 1,	2,3,4,5,6,7,9 and 10 a	are gone.									
8 is good but no nail found. 11,12,13 and 14 are in	good condition.										
I found nothing to dispute the location of this corner	r. ·										
C. Description of monument for corner a											
I replaced the boat spike in the monument box with this as a careful and faithful reestablishment of the	a 5/8" x 18" iron rod v position of the origina	with a 2 ½" Aluminum cap stamp al corner.	oed "Mason	Cour	nty Mon	ument P	LS 176	34". Tac	cepted		
Power pole N47W 62.24' (Ex. 16d nail w/MSHD s Most westerly guard rail post on N. side rd. N80E 1 Power pole S48E 81.17' (Ex. 16d nail w/MSHD sh Power pole S33E 185.57' (Ex. 16d nail w/MSHD s K-1 of T17N, R18W is East 26.53'	50.28" (set 60d spike iner E. side)	e on S. skde)			Till S		H L. P LAND RVEYO	938 8	11111111111111111111111111111111111111		
Signed by		Date	2000	2	- / 4	1 -	No. 7-6-3	4 , 6			
Surveyor's Michigan License No. 17634			FORM APPROV	_	MICHGAN	TATE BO	(ROOP (S)	O FURNEY	ORS, JAR	28,	
Approved by Peer Review Group on 8-10 Kenneth L. Ross, County Representative	- 2000 + 1		1971 REVISED HAY REVISED JAK ADAPTED FOR	, 1965		FING MARC	(422) 5684 H , 1993	、 ·			