


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Mason COUNTY
T 19 N R 18 W

DESCRIPTION OF CORNER SW Corner Section 20
CORNER MONUMENT Set 1"x8' Pipe and Post
DATE MONUMENT PLACED AND WITNESSED 11-11-71
WITNESSES TO CORNER.....



NW Cor. Saltwell Foundation S 56 E 311.8'
Face of Power Pole S 76 W 146.4'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored according to survey data recorded in 1930s Highway Department survey, and a property survey by Dow Chemical for salt well location in Sec. 29. Previous monument lost through dune erosion. This point apparently found acceptable in previous surveys.



SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR #10068

DATE 11-18-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68